

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 2 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1551)</p> <p>-----</p> <p>Set standard 1/4 sec. post, from which A W.Oak 24" dia., bears S.73°E., 515 lks. dist. No tree South and West of line.</p>
<p>BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13672)</p> <p>-----</p> <p>Point for the stan. ¼ sec. cor. of sec. 2, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.</p>
<p>Survey by Les Roberts - For: International Paper Co. - Oct/Dec 1982 - M 90-29 and C.S. File 58/280</p> <p>-----</p> <p>No evidence found of original corner. Set 5/8" x 30" Iron rod at proportionate distance. Rod has yellow plastic cap mkd. "Roberts L.S. 1039" Rod buried 1.0 ft. New BTs -15" Oak S.57°E., 282.2 ft. - scribed.           18" Oak S.77°E., 270.8 ft. - scribed. Incorrect corner bears S.89°46'12"E., 0.89 ft. I <u>removed</u> incorrect set pin on 12/30/82.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 6/25/2002 - C.S. File 66/34-14</p> <p>-----</p> <p>Found - 1982 iron rod located by metal detector under ground, did not dig up. Corner falls in hay field (M90-29)           18" now 22" dia., W.Oak with a fully healed double blaze bears S.77°E., 270.8 ft. (1982)           15" now 18" dia., W.Oak stump tipped out of ground, root hole bars S.57°E., 282.2 ft. (1982)           OBTs looked for not found.</p> <p>New - 18" dia., W.Oak double blazed &amp; scribed "¼ S2 CS BT" bears S.55°E., 290.6 ft.       18" dia., W.Oak double blazed &amp; scribed "N¼ S2 CS BT" bears N.62°E., 401.0 ft. (Note: BT is in T2S R8W Sec. 35)       Compass decl. 17¼°E.</p>