

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2634)

Set Maple post, 5 ft. long, 5" dia., 20" in the ground for the 1/4 sec. cor. between secs. 29 & 30, from which
 A Fir, 12" dia., bears N.20°E., 19 lks.
 A Fir, 18" dia., bears S.75°W., 24 lks.

Douglas Co. Surveyors Office - Larry E. Monrean - Pete Earle - 10/26/1973 - C.S. File 56/39-11

Found - 2" iron pipe 23" above ground.
 36" stump, bears N.30°E., (rec. N.20°E.) 12.8 ft. (rec. 12.54 ft.) scribed "1/4 S S29 BT"
 Other BT, a stump out of ground, badly burned & rotted lies almost directly over corner.
Set - Brass cap at corner inside iron pipe mkd:
 COUNTY SURVEYORS T23S R9W
 OFFICE 1/4
 1973 S 30 | S 29
 6" D.Fir, bears N.3 1/2°E., 18.8 ft. scribed S29 CS BT
 8" Fir, bears S.49°W., 54.5 ft. scribed T23S R9W S30 CS BT.

Fd. & used on BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16223-4)

Fd. Ok M113-34 A&B, 5/1991

Wayne R. Donovan, June 27, 1995 - C.S. File 63/161-30

Condition report only
Found - 2" brass cap by County Surveyor's Office
 44" Fir stump, bears N.26°W., 55.3 ft. (w/BT tag) not of record
 7" Fir snag, bears N.3 3/4°E., 18.2 ft. (w/BT tag)
 30" Fir stump, bears N.27 1/2°E., 13.0 ft. (visible scribing)
 36" Fir stump, bears N.85 3/4°E., 41.2 ft. (w/BT tag) not of rec.
 18" Fir, bears S.49 3/4°W., 53.9 ft. (w/BT tag)
 10" Fir, bears S.80°E., 26.7 ft. (blazed and scribed "1/4 S29 BT")
Note - All BT's from M113-34 A&B.
 Corner lies on a flat area southeast of cat road.

continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Boyd W. Peterson, Cadastral Surveyor & Richard L. Sanford, Survey Technician, under Group #1709, surveyed Aug. 1993/Feb. 1995 - (DCS0 Vol. 52 Page(s) 19664-5)

From the ¼ sec. cor. of secs. 29 & 30, monumented with an iron post, 2" diam., firmly set, projecting 16" above the ground, with brass cap mkd.

County Surveyors Office
T23S R9W

¼
S 30 | S 29
1973

from which the remains of an original bearing tree

A fir stump, 36" diam., bears N.30°E., 19 lks., with scribe marks ¼ S29 BT visible on open face. and bearing trees mkd. by County Surveyors Office in 1973, reported by Bowder

A fir, 18" diam., bears N.3½°E., 28½ lks., with healed blaze.

A fir, 20" diam., bears S.51 3/4°W., 82 lks., with healed blaze. (Record, S.49°W.) and a bearing tree of which I have no record

A fir, 10" diam., bears S.74°E., 40½ lks., with scribe marks ¼ S29 BT visible on an open blaze.