

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2636)

Set Maple post, 5 ft. long, 5" dia., 20" in ground for the sec. corner between secs. 17 & 18, from which
A Hemlock, 30" dia., bears N.50°E., 37 lks.
A Hemlock, 36" dia., bears S.72°W., 40 lks.

BLM Dependent resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group #703 surveyed July 1969 - May 1970 - (DCSO records Vol. 35 Page(s) 14563-4)

Point for ¼ sec. cor. of secs. 17 & 18, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
T23S R9W
¼
S 18|S 17
1969

from which
A Hemlock, 20" dia., bears N.83°E., 47½ lks. mkd: ¼ S17 BT
A Hemlock, 13" dia., bears S.64 ¾°W., 45 lks., mkd: ¼ S18 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2074, surveyed April/June 2004 - (DCSO records Vol. 54 Page(s) 21263-4)

The ¼ sec. cor. of secs. 17 & 18, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.
from which the remains of the BTs mkd. by Jelley and Steward
A hemlock, 24" dia., bears N.83°E., 31.4 ft., with a healed blaze
A roothole bears S.64¾°W., 29.7 ft., alongside of which is a down decayed hemlock, size indeterminate, no marks visible.
and a new bearing tree
A fir, 7" dia., bears S.43½°W., 26.5 ft., mkd. ¼ S18 BT.
Each new bearing tree has a 2½"x¼" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.