

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 5 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2622)</p> <p>-----</p> <p>Set a Dogwood post for ¼ sec. cor., from which A Fir, 30" dia., bears South 21 lks. A Fir, 36" dia., bears N.60°W., 48 lks.</p>
<p>GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2695)</p> <p>-----</p> <p>the post is gone, but the BTs are standing, but having no description in field notes, could not re-establish same.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - June 1970 - C.S. File 54/60-52</p> <p>-----</p> <p>Reported as not found. F.A.P. (?) called for snag - we do not find any snag as called for - very dense brush.</p>
<p>BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23222)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of sec. 5 only, on the N. bdy. of sec. 8, at proportionate dist.; there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 23 S R 9 W ¼ S 5 ----- 2014</p> <p>from which new bearing trees A W.Fir, 20" dia., bears N.74½°E., 35.5 ft., mkd. X BT. A W.Fir, 12" dia., bears N.73½°W., 60.2 ft., mkd. ¼ S5 BT. Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description. Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description. An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.</p>
<p style="text-align: right;">1</p>