

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Cor. Secs. 8, 9, 16, & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2660)

Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 8, 9, 16, & 17, marked T23S S9 on NE; R9W S16 on SE, S17 on SW and S8 on NW face, with 4 notches on S and E edges, from which
A Fir, 40" dia. bears N.89°E., 72 lks. mkd: T23S R9W S9 BT
A Fir, 26" dia. bears S.54°E. 51 lks. mkd: T23S R9W S16 BT
A Fir, 6" dia. bears S.46°W. 103 lks. mkd: T23S R9W S17 BT
A Fir, 30" dia., bears N.9°W., 80 lks. mkd: T23S R9W S8 BT
Cor. stands 60 ft. below top of ridge.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - June 1970 - C.S. File 54/60-60

Found - Orig. 30" Fir, now 40" sawed stump, N.9°W., 52.8 ft., partial axe blaze on bark, chopped open by someone, no scribe. Also has old yellow tag dated 1945 & numerous brag marks.
Orig. 26" now 36" Fir, badly decayed & burned, S.54°E., 33.7 ft., no scribe found.
Orig. 40", now 48" Fir, badly decayed & burned N.89°E., 47.5 ft., no scribe found.
No trace of orig. BT to SW, call of 2 ch. to E. was on trail, I assume trail was on ridge top. The approx. 60 ft. elevation below top of ridge also looks ok. Call on creek to S. fits OK by pacing. This position has been recognized as corner point for at least 25 years. Also find remains of very old & badly decayed sq. post.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R9W
OFFICE 1970 S 8 | S 9
S 17 | S 16
10" D.Fir S.19°W., 10 ft., mkd: T23S R9W S17 CS BT
16" D.Fir S.76°E., 12.5 ft., mkd: T23S R9W S16 CS BT
18" D.Fir N.31°W., 23.0 ft., mkd: T23S R9W S8 CS BT
11" D.Fir N.26°E., 40.3 ft., mkd: T23S R9W S9 CS BT
This corner lies on steep westerly slope in dense brush.