

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2622)

-----  
Set fir post 5 ft. long 6" dia., 24" in the ground for ¼ sec. cor. from which  
A Fir, 48" dia., bears S.20°E., 90 lks.  
A Fir, 48" dia., bears S.15°W., 85 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 11/24/1969 - C.S. File 54/60-6

-----  
Reported as not found.  
We find no OBTs, apparent old burn.

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23221)

-----  
Point for the ¼ sec. cor. of secs. 4 & 5, at proportionate; there is no remaining evidence of the original cor.  
Set a stainless steel post, 28" long, 2½" dia., 28" in the ground, with brass cap mkd.

T 23 S R 9 W  
                  ¼  
                  S 5|S 4  
                  2014

from which new bearing trees  
A W.Fir, 9" dia., bears N.77½°E., 58.5 ft., mkd. ¼ S4 BT.  
A maple, 18" dia., bears S.51½°W., 18.7 ft., mkd. ¼ S5 BT on bark.

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.