

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2689)

A Fir, 9" in dia. for 1/4 sec. cor. I marked 1/4 S4 on N side and 9 on S side, from which:

A Fir, 12" dia., bears North 7 lks., mkd: 1/4 S4 BT.

A Fir, 6" dia., bears S.28°E., 5 lks., mkd: 1/4 S9 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - 1/24/1974 - C.S. File 56/43-9

Found - Orig. 6" now 16" D.Fir snag, rotten & showing good scars on north & south faces. I open & find scribing "1/4S" on north face & no scribing on south face.

12" now 24" D.Fir snag, rotten, bears N.12°E., 4.3 ft. (rec. 4.6 ft.) with partial scribe visible. I open completely & find scribing "1/4 S3 BT". The "3" in the scribe does not correspond with the field notes.

12" D.Fir snag, rotten, bears S.23°E., 5.0 ft. (rec. S.28°E., 3.3 ft) scribed area decayed & fallen.

From this location, an old line of blazes extends to the east and a small pond is located as called for to the West. I remove the deteriorating orig. corner tree and

Set - Brass cap mkd: COUNTY SURVEYORS T23S
OFFICE 1/4 S 4
1974 S 9

26" D.Fir, bears S.39°E., 45.5 ft., scribed S9 CS BT

22" D.Fir, bears N.40°E., 70.4 ft., scribed S4 CS BT

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23220)

The 1/4 sec. cor. of secs. 4 & 9, perpetuated by the Douglas Co Surveyor's Office, in 1974; monumented with an iron post, 1 1/2" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed fir snag, 15" dia., bears N.12°E., 4.6 ft., with illegible scribe marks visible on open blaze (Record, North).

A roothole bears S.28°E., 3.3 ft., with decayed fir remains.

and the remains of the BTs mkd. by the Douglas County Surveyor's Office
continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole bears N.40°E., 70.4 ft., alongside of which is a down fir, 23" dia., with a healed blaze.
A fir, 37" dia., bears S.39¾°E., 45.4 ft., with a healed blaze.
and a new bearing tree
A fir, 32" dia., bears N.43¾°E., 97.2 ft., mkd. ¼ S4 BT.
Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.
Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.
An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.