

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2688)

-----  
Set a Hemlock post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S3 on N face and 10 on S face, from which:  
A Fir, 40" dia., bears N.12°E., 74 lks., mkd: ¼ S3 BT.  
A Fir, 40" dia., bears S.18°W., 21 lks., mkd: ¼ S10 BT.

Douglas Co. Surveyors Office - Larry E. Monrean - Stephen J. Flause - 4/19/1984 - C.S. File 62/18-1

-----  
Reported as not found.  
Found - Orig. monument not found.  
A wooden post temporarily marking corner position.  
Post has been recently set with temporary marks on hewn sides.  
A Fir stump about 6 ft. high and 44" dia., bears N.12°E., 48.8 ft. This stump has two BT tags, one is dated 4-17-84, the older tag is dated 8-31-62 with initials RY, this is a BLM tag. This stump has several scars. Before opening this stump we looked for evidence of bark scribing, none was found. We opened the stump over a large area facing the noted post, no evidence of a blaze or scribing was found. Two axe notches were found about 2 ft. above ground, level with each other and about 1½ ft. apart. 20± growth rings were counted in the good wood covering these notches, another layer of decayed wood is located under the bark about 25 growth rings were counted in this layer. This would place the date of the notches about 45 years prior to the date the tree was cut down. This area appears to have been logged 20 to 25 years (approx.) prior to my visit. This would date the age of the axe marks at about 65 to 70 years. The orig. survey was done in 1899.  
Decayed & broken remains of a tree (size indeterminable) were found S.18°W., 13.9 ft. from the temporary post.

Comments -  
An exhaustive search for orig. evidence was not made in this area. Our efforts were spent on evaluation of the possible NE BT.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Richard Hintz, LS 497 - For: International Paper Co. - June 1984 - M 97-6

-----  
Set - A 3" x 3" x 4' Fir post, S.12°W., 48.8 ft. from what I believe to be the orig. 40" dia., Fir BT, now a 6 ft. high tree, consisting of rotted wood and fir bark, bears S.18°W., 15 ft.±. The position of my post is 175 ft. east of a creek, course NE, which fits the orig. call of 2.62 chains. See corner restoration form CS 62/18 (DCSO)  
Attached an aluminum tag to the top of the post marked PLS 497.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Dec. 10, 1985 - C.S. File 62/29-1

-----  
Found - Wooden staub w/hewn sides & temporary ink markings, with a 3"x3" square alum. tag. on top. 1984  
Orig. BT, 40" now 44" dia., 6 ft. high D.Fir stump previously opened blaze shows 2 blaze axe marks, bears N.12°E., 48.8 ft.  
Orig. BT, 40" now size indeterminable decayed Fir, bears S.18°W., 13.9 ft.  
Set - A DCSO disk on an IP that protrudes 5" above ground with Hintz wooden staub placed alongside south side. Disk marked "Douglas County Surveyors T23S ¼ S3 S10 R9W 1985"  
IP is set in position determined by Hintz survey M97-6.  
8" D.Fir double blazed & scribed "¼ S10 CS BT" bears S.32°W., 11.6 ft.  
8" D.Fir double blazed & scribed "¼ S10 CS BT" bears S.81¼°W., 13.0 ft.  
7" D.Fir double blazed & scribed "¼ S3 CS BT" bears N.25½°E., 35.9 ft.  
7" D.Fir double blazed & scribed "¼ S3 CS BT" bears N.49°E., 28.5 ft.  
Note - The Hintz survey adds evidence to support the position. Note the proximity of corner to mid point between the SE & SW corners, sec. 3; also note dist. checks well to the creek, (175 ft West) Old tags show apparent use of probable BT 10 years past.  
Corner lies on a NW slope.