

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 26 & 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2671)  
-----  
A point, 120 ft. below top of divide, I set a Fir post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S27 on W face and 26 on E face, from which:  
A Fir, 14" dia., bears S.6°E., 112 lks., mkd: ¼ S26 BT.  
A Fir, 5" dia., bears N.7°W., 28 lks., mkd: ¼ S27 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel - Mike Stone - Oct. 1964 - C.S. File 53/84-2  
-----  
Found - 29" D.Fir S.6°E., 73.9 ft. prev. opened, good scribing visible "¼ S26 BT"  
Did not find NW BT.  
Note - Corner position falls on bare rock face, very steep slope, impossible to set corner here.  
Set - Wit. cor. S. 75.0 ft. of ¼ cor. - Drove 3/4" rod at wit. cor.  
27" D.Fir N.41°W., 11.7 ft., mkd: WC ¼ S27 CS BT.  
29" D.Fir N.85°E., 7.8 ft. from wit. corner.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - March & April 1967 - C.S. File 54/60-2  
-----  
Found - 27" D.Fir, now 5 ft. high stump N.41°W., 11.7 ft., scribe visible on pitched blazes. See 1964 ren. (See other BT below)  
No trace of I.Rod or other BTs due to slide & logging, ¼ cor. falls on nearly vertical rock face. Destroyed WC was 75 ft. south of true corner. We set new WC out of slide area, 105 ft. south of true corner.  
Set - Brass cap at WC mkd: COUNTY SURVEYOR T23S R9W OFFICE 1967 ¼ S27|S 26  
WIT. COR. TO ¼ COR. 105' N TO CORNER  
No live trees near:  
9" Hemlock stump S.78°E., 28.2 ft., mkd: WC ¼ S26 CS BT  
18" D.Fir stump N.78°W., 34.4 ft., mkd: WC ¼ S27 CS BT.  
27" D.Fir stump bears N.10½°W., 38.7 ft. (1964)

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 26 & 27

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23302-3)

-----  
The 1/4 sec. cor. of secs. 26 & 27, perpetuated by the Douglas County Surveyor's Office in 1964 and again in 1967, from original evidence no longer in existence; determined at reported bearing and distance from the witness cor. set by the Douglas County Surveyor's Office in 1967

An iron post, 1" dia., firmly set, projecting 6" above ground, bears South, 105.00 ft., with a brass cap mkd.

COUNTY SURVEYORS OFFICE T23S WIT. COR. TO 1/4 S27|S26 R9W  
105 FT N TO COR. 1967 and an arrow pointing to the cor.

This monument now functions as a reference monument. from the witness cor., the remains of a bearing tree mkd. by the Douglas County Surveyor's Office in 1964 for a witness cor. no longer in existence, reused in 1967

A decayed fir stump, 25" dia., bears N.10°W., 39.2 ft., with scribe marks WC 1/4 S27 visible on open blaze.

and the remains of a bearing tree mkd. by the Douglas County Surveyor's Office in 1967

A decayed fir stump, 18" dia., bears N.77 3/4°W., 34.0 ft., no marks visible.

At the corner point

Set a brass tablet, 3 1/4" dia., 3 1/2" stem, cemented in a drill hole in solid rock, with top mkd.

T 23 S R 9 W  
1/4  
S 27|S 26  
2014

and new bearing trees

A fir, 10" dia., bears N.43°E., 17.5, mkd. 1/4 S26 BT.

A fir, 17" dia., bears S.22 3/4°E., 59.7, mkd. X BT.

There are no new bearing trees available within limits in sec. 27. Drive an aluminum angle iron 5 ft. E. of the cor.