

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2657-8)

-----

Set a maple post, 3 ft. long, 4" sq., 24" in ground, for cor. to secs. 10, 11, 14, & 15 marked T23S S 11 on NE, R9W S14 on SE, S15 on SW, & S10 on NW faces, with 2 notches on E and 4 notches on S edges; from which

- A Fir, 40" dia., bears N.55°E., 23 lks., mkd: T23S R9W S11 BT.
- A Hemlock, 36" dia., bears S.43°E., 58 lks., mkd: T23S R9W S14 BT.
- A Hemlock, 18" dia., bears S.51°E., 31 lks., mkd: T23S R9W S15 BT.
- A Chittenwood, 6" dia., bears N.72½°W., 21 lks., mkd: T23S R9W S10 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Jan. 1967 - C.S. File 54/12-4

-----

Found - Orig. 18" now 46" Hemlock S.51°W., 20.5 ft., prev. opened many years ago or never completely healed over, shows "3 9W T" scribe on badly rotted face. No trace of other orig. BTs.

Set - Brass cap at cor. Mkd: COUNTY SURVEYORS T23S R9W OFFICE 1967 S 10 | S 11  
S 15 | S 14

46" Hemlock S.51°W., 20.5 ft., rescribed: T23S R9W S15 CS BT

5" Hemlock S.65°E., 13.6 ft., mkd: S14 CS BT

28" Hemlock N.53°E. 35.2 ft. mkd: T23S R9W S11 CS BT

No suitable trees in Sec. 10

Note - This corner lies approx. 135 ft. W. of Otter Creek, course NE.

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23217-8)

-----

The cor. of secs. 10, 11, 14, & 15, perpetuated by the Douglas County Surveyor's Office, in 1967; monumented with an iron post, 1 1/4" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

- A very decayed hemlock stump, size indeterminate, bears S.43°E., 38.3 ft., no marks visible.
- A decayed hemlock stump, size indeterminate, bears S.51°W., 20.5 ft., no marks visible.

continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of the BTs mkd. by the Douglas Co. Surveyor's Office

A decayed hemlock stump, 19" dia., bears N.50½°E., 35.4 ft., no marks visible.

A decayed hemlock stump, 6" dia., bears S.66°E., 13.5 ft., no marks visible.

and new bearing trees

A fir, 14" dia., bears N.13°E., 14.9 ft., mkd. T23S R9W S11 BT.

A fir, 11" dia., bears S.65¾°E., 11.6 ft., mkd. T23S R9W S14 BT.

A fir, 10" dia., bears S.65½°W., 17.7 ft., mkd. T23S R9W S15 BT.

A fir, 12" dia., bears N.32¾°W., 20.9 ft., mkd. T23S R9W S10 BT.

From the corner

S.89°10'35"E., 130 ft., Otter Creek, 10 ft. wide, course N.50°E.

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.