

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, T24-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2625-26)

Set Fir post 40" long, 5" dia., 18" in the ground, for the corner to secs. 2 and 3 on N. bdy. T24-9, from which
A Fir 60" dia., bears N.1°E., 8 lks. dist.
A Fir 60" dia., bears S.70°E., 21 lks. dist.
A Fir 8" dia., bears S.38°W., 53 lks. dist.
A Fir 12" dia., bears N.60°W., 47 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2641)

The cor. of secs. 2 and 3, the original post is standing, badly decayed, it is a Fir post 5" sq., 24" high, marked and witnessed as described by the surveyor general, witness trees marked T22, I destroyed all marks, referring to this Tp.

Douglas Co. Surveyors Office - J.W. Byron - (probably 1967) -C.S. File 54/60-57

No original evidence found. No cor. monument found.
Found 28" Fir stump S.70°W., 43.7 ft. with "W" nail and tag.

Tony Hostetter - For: Weyerhaeuser Co. Co. - March 2010 - C.S. File 65/69-5

Found - 1/2" conduit & 2 60" fir windthrown stumps which appear to have been in the correct locations (when standing) to match GLO records for 2 of the 3 orig BTs. The stump listed at S.70°E., 21 lks has a Weyerhaeuser tag which reads N.70°W. 13.0 ft. from which
New BTs- 17" fir stump, Weyco tag & spike, bears: S.62°E., 18.2 ft to spike.
12" fir stump, Weyco tag & spike, bears: S.36°W., 26.2 ft to spike.
20" fir stump, Weyco tag & spike, bears: N.07°W., 16.9 ft to spike.
Corner location (GARMIN 60CSX GPS)
43°30'58.9" N
123°44'19.4" W