

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 668117

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T23-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2530)

I set a post 4½ ft. long, 4" sq., 24" in the ground, for closing corner at SW. corner to T23S R8W, marked CC T23S on N.; R8W S31 on E.; and R9W S36 on W.; with 6 notches on N. and E. sides, from which

A Fir 24" dia., bears N.28°E., 60 lks. dist. mkd. T23S R8W S31 BT.

A Fir 24" dia., bears N.25°W., 28 lks. dist. mkd. T23S R9W S36 BT.

A Fir 16" dia., bears S.58°W., 14 lks. dist. mkd. T23S R8 & 9 W CC BT.

Douglas County Surveyors Office - Gary Langlitz and Peter Earle, crew - C.S. File 56/51-9 - May 14, 1974

Corner searched for, not found.
Searched in area indicated by topographic and aerial maps. Found Weyerhaeuser line crossing tag along road and found tree with Weyerhaeuser nail in a notch. Tag on tree gave bearing and distance (not of record) to possible corner location. We open tree and find no evidence of scribing. Some nearby trees have cruisers marks on them. This area is on a steep slope that shows signs of soil movement. Most old growth trees have uprooted.
WE DO NOT MONUMENT.