

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, (East)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #688 dated June 9, 1898 (DCSO records Vol. 6 Page(s) 2616)

-----  
 At the point 300 ft. below mountain ridge, I set a sandstone 14x8x6 ins., 10" in the ground for cor. of secs. 25 and 36, marked with 5 notches on N. and 1 notch on S. edges, from which

A Fir 28" dia., bears S.89°W., 19 lks. dist. mkd. T23S R9W S36 BT.

A Fir 20" dia., bears N.80°W., 50 lks. dist. mkd. T23S R9W S25 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1967 - C.S. File 54/12-7

-----  
 Found - No trace of rock called for.  
 Orig. 28" now 28" Fir snag, S.89°W., 12.5 ft., shows "T23S R9W S36" on unhealed blaze.

Orig. 20" now 34" Fir, alive, N.80°W., 33.0 ft., shows good scar. (Rescribe "T23S R9W S25 CS BT")

Set Brass cap at cor. mkd: County Surveyors Office

R	T	23	S	R
9	S	25		8
W	S	36		W
1967				

New BT - 24" D.Fir S.75°W., 17.4 ft. mkd. T23S R9W S36 CS BT. Corner lies on very steep NE. slope approx. 540 ft. S. of creek.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - July 28, 1992 - C.S. File 64/31-4

-----  
 Found - A 2½" DCSO brass cap, properly mkd., dated 1967 on 1½" O.D. Iron pipe, protruding 11" above ground.  
 28" now rotted D.Fir stump of indeterminable size, no blazes or scribing found, bears S.82°W., 12.5 ft. (Rec. S.89°W., 12.5 ft.) (orig. BT.)

20" now 36" dia. D.Fir with a fully healed double blaze, bears N.80°W., 33.0 ft. (agrees w/rec.) Orig. BT.)

24" now 26" dia. 10 ft. tall D.Fir snag with a fully healed double blaze, bears S.75°W., 17.4 ft. (agrees w/rec)

New BTs- 12" dia. Hemlock, double blazed and scribed "T23S R9W S25 CS BT", bears N.30°W., 22.8 ft.

5" dia. D.Fir, double blazed and scribed "X BT", bears N.79°E., 23.0 ft.