

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2710)

Set Cedar post, 5 ft. long, 5 ins. dia., 20" in ground for the 1/4 sec. cor. between secs. 26 & 35, from which
 A Cedar, 10" dia., bears N.78°E., 64 lks.
 A Fir, 18" dia., bears N.23°W., 18 lks.

Elliott State Forest Corner Records by Federal Civilian Conservation Corp (CCC) 8/1933 - FB 119 Pg. 9 (Filed 4/24/1958 C.S. File 49/80-1 pg 8)

No trace of OBTs (burn) at 27+50 ch. an 18" Cedar mkd. & blazed by Cruiser - 18 ft. No. of line.
Set - 3"x3"x4' Fir post for 1/4 corner.
 20" Fir N.65°E., 44 ft.
 18" Fir N.39°E., 39 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel - Mike Darby - Mike Stone - May & June 1964 - C.S. File 49/60-5 See also C.S. 49/80-1 pg 2 & 3 for a 7/1957 & 9/1957 search by DCSO

Found - D.Fir (now 42" dia.) N.65°E., 44.0 ft. scribing visible. 1933
 D.Fir (now 32" dia.) N.39°E., 39.0 ft. face open, but pitched over.
Set - Brass cap mkd: County Surveyors Office 1964 T23S R10W 1/4S26/S35
 6" Hemlock S.26°W., 24.7 ft. mkd: 1/4 S35 CS BT
Note - Found old, rotted Cedar stump scribed "1/4S" on E face S.33 1/2°W., 28.2 ft., which I believe to be an OBT - does not face right for call in government notes for BT - No other old tree found to match it, even if bearing given is in wrong quadrant.
Corner renewed by me, is re-renewal of corner as set by Oregon State Bd. of Forestry only, not renewal of orig. corner.

Fd. Ok by G. Miller, 6/10/1984 M 97-68