

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO recs. Vol. 7 Page(s) 2705)

-----  
Set Maple post, 4 ft. long, 5 ins. dia., 18" in ground for the 1/4 sec. cor. between secs. 13 & 24, from which  
A Maple, 14" dia., bears S.5°E., 31 lks.  
A Fir, 36" dia., bears N.10°W., 34 lks.

BLM Resurvey by Donald Beck, Cadastral Surveyor, under Group #658, surveyed Oct/Nov. 1967 (DCSO records Vol. 36 Page(s) 14605)

-----  
Point for 1/4 sec. cor. of secs. 13 & 24, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap marked:

T23S R10W  
1/4     S 13  
          S 24

from which  
A Maple, 18" dia., bears N.50°E., 28 lks., mkd: 1/4 S13 BT.  
A Fir, 24" dia., bears S.8°E., 56 lks., mkd: 1/4 S24 BT.

Fd. Ok by Lloyd Smith 9/29/1981 M89-40

Fd. & used on BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor, under Group # 1459, surveyed Aug.. 1988 - (DCSO records Vol. 49 Page(s) 18730)

James McIntosh - For: State of Oregon, Dept. of Forestry - Aug. 2004 - M 145-50

-----  
Found - BLM P/C, 1967 (in place)  
18" Maple N.50°E. 28 lks (now 28" X 2' high stump in place, face rotted)  
24" Fir S.08°E. 56 lks (now 27" in place, face closed)  
Metal fence post S.74°E., 2.7' to base (no record)  
New - WP S.30°W., 3.0' to base  
WP N.60°W., 3.1' to base