

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 36; & 31, T23-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2629)

Set a Chittem wood post 5 ft. long, 5" dia., 20" in ground for the ¼ sec. corner between secs. 31 and 36, from which
A Fir 36" dia., bears East, 18 lks. dist.
A Fir 36" dia., bears S.2°W., 18 lks. dist.

Theodore S. Ellingsen - For; Menasha Wooden Ware Corp. - Nov. 18, 1954 - C.S. File 41/327

Set a 3/4" Iron pipe.
Scribe one new BT to replace one which is now rotten:
A Fir 41" dia., bears N.19°E., a distance of 30 ft., mkd. ¼ S31 BT 329.

Cor. Fd., Dec. 1976 by Michael McDowell - M 62-48

BLM dependent resurvey by Boyd W. Peterson, Cadastral Surveyor & Richard L. Sanford, Survey Technician, under Group #1709, surveyed Aug. 1993/Feb. 1995 - (DCSO Vol. 52 Page(s) 19658)

Beginning at the 1/4 sec. cor. of secs. 31 and 36, on the W. bdy. of the Tp., perpetuated by Ellingsen, in 1954, and S. McDowell, in 1976; monumented with an iron pipe, 3/4 in. diam., firmly set, projecting 4 ins. above ground, from which the remains of an original bearing tree:

A fir stump, 48 ins. diam., bears S.2°W., 18 lks., no marks visible.
and the remains of a bearing tree mkd. by Ellingsen
A fir stump, 46 ins. diam., bears N.19°E., 48½ lks., w/healed blaze.

At the corner point
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:

T23S
¼
R10W R9W
S 36|S 31
1993

and a new bearing tree
A fir, 7 ins. diam. bears S.40¼°E. 87 lks., mkd. ¼ S31 BT.
No other suitable accessories available within limits.
Deposit iron pipe and a white "DEEP-1" magnetic marker at base of stainless steel post.

continued next page

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 36; & 31, T23-9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Estabrook Land Surveying - For: Weyerhaeuser Co. -
5/1/2025 - M186-3

-
- Found - 2½" Iron pipe with brass cap.
 - 42" Fir stump, rotted with no visible marks, bears N.19°E. 30.0'
 - 20" Fir stump, rotted with no visible marks, bears east 12.0'
 - 36" Fir stump, rotted with no visible marks, bears S.02°W. 12.0'
 - New - 19" Fir, faced & scribed "¼ S31 BT" with x-chop & tag bears N.31°E. 7.7' to a spike at side center.
 - 9" Fir, faced & scribed "¼ S31 BT" with x-chop & tag bears S.22°E. 11.5' to a spike at side center.
 - 20" Fir, faced & scribed "¼ S36 BT" with x-chop & tag bears S.62°W. 23.8' to a spike at side center.
 - 16" Fir, faced & scribed "¼ S36 BT" with x-chop & tag bears N.47°W. 21.5' to a spike at side center.