

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 103100

PRIMARY CORNER DESCRIPTION 120 1/16 SEC 6 T25-1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #1061 surveyed April/June 1981 - (DCSO records Vol. 45 Page(s) 17360)

Point for the 120 1/16 sec. cor of sec. 6 only, T25S R1W is at proportionate dist. on the N bdy of sec. 6.
Set an iron post, 28" long, 2½" diam., 24" in the ground, with brass cap mkd.
$$\frac{120 \ 1/16 \ S \ 6}{1981}$$

from which
 A fir, 5" diam. bears S.81°E. 15 lks mkd. 120 1/16 S6 BT
 A fir, 5" diam. bears S.51°W. 24 lks mkd. 120 1/16 S6 BT

David Edwards for Seneca Jones Timber Co. 8/11/2008 - M156-53

Found - 6" fir S.51°W. 15.8 ft.
 12" fir S.81°E. 9.9 ft.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed Sept./Nov. 2011 - (DCSO records BLM Plat T25-1W 2012-2 & Vol. 58 Pgs 22945-6)

The 120 1/16 sec. cor. of sec. 6 only, on the N. bdy. of the Tp., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd. from which the bearing trees mkd. by Jelley
 A fir, 16" dia., bears S.81°E., 9.9 ft., with a healed double blaze.
 A fir, 7" dia., bears S.47½°W., 15.8 ft., with a healed double blaze.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 11/20/2025 - C.S. File 67/61-41

Found - ¾" BLM brass cap proj 4".
 Burned, dead 7" fir. S.51°W. 15.8 ft. add ¾" mag nail, right side center. Fully healed double blaze.
 Burned, dead 17" x 15ft. Fir snag S.81°E. 9.9 ft. fully healed single blaze. Add ¾" mag nail right side center.
 Galvanized post S.80°E. 2.8ft.
Notes - Area badly burnt 9/2020.
 Mon is near westerly edge of bench ground clearcut in S.E. quad. Rest burnt older reprod.
 Mon is approx 175 feet east of gravel road.
Compass decl. 14¼°E. TRIMBLE GEO XT POSITION
43.43757723 N. 122.80736291 W. _____