

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 31, T23-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2134)

Set basalt stone 24x20x12 ins., 18" in the ground mkd. $\frac{1}{4}$ on N. face, for $\frac{1}{4}$ sec. cor., from which
A Fir 6" dia., bears N.62°W., 7 lks. dist. mkd. $\frac{1}{4}$ S BT.
A Fir 4" dia., bears S.35°W., 8 lks. dist. mkd. $\frac{1}{4}$ S BT.

Frank Williams, Weyerhaeuser Co. - Aug. 1975 - C.S. File 59/38-20

Original stone not identified; several large stones have slid down steep hillside to creek bottom, many are fractured. NW. BT, not found. Found 8"x8' Hemlock snag (not Fir), down with curved portion of root still in its original position. Overgrowth was chopped away to expose scribed " $\frac{1}{4}$ S" on upper face and "BT" on lower face.
Drove 3" x 5 ft. Cedar post N.35°E., 5.3 ft. from center of roothole of down scribed BT.
This corner will soon be further monumented by a current Triangle Engineering Company subdivision of Sec. 6.

Douglas County Surveyors Office - C.S. File 59/38-20 - Aug. 25, 1977

Corner searched for, not found.
Weyerhaeuser Surveyor, Frank Williams found scribed BT apparently buried in new logging road fill.