

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 141100

PRIMARY CORNER DESCRIPTION N. 1/4 cor. for Sec. 6 only, T25-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #477, surveyed July 1962 - (DCSO records Vol. 45 Page(s) 17359-60)

The point for the ¼ sec. cor. of sec. 6 only, T25S R1W, is at proportionate dist. on the N. bdy. of sec. 6.
Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd. T 24 S R 1 W

1/4 S 6
T 25 S R 1 W
1981

from which

A Fir 16" dia., bears S.33½°E., 48 lks. dist. mkd. ¼ S6 BT.

A Fir 6" dia., bears N.47½°W., 51 lks. dist. mkd. X BT.
(The ¼ sec. cor. of sec. 31, T24S R1W, bears N.89°39'W., 0.47 chs. dist.)

FD. BC & 2 BTs by D. Edwards, 8/2008 - M156-53

Gerald Nygren - For: Barnes & Associates - 12/2018 - M175-10

Found - 1981 BLM brass cap per rec. 0.93' south of township line.

16" fir, now 32" bears S.33°30'E., 31.7' healed blaze (1981)

6" Fir, Now 20" bears N.47°30'W., 33.7' healed blaze (1981)

Set - 5' galv. Metal post, east, 5.0'