

PRIMARY CORNER DESCRIPTION Cor Secs 19, 20, 29, & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A root hole, bears N.33°W., 10 lks., with down cedar alongside, 22" dia., no marks visible.
and the remains of a BT mkd. by Tracy:

A sawed hemlock stump 12" dia., bears N.9°W., 35 lks., no marks visible.

and new BTs:

A sawed fir stump, 40" dia., bears S.72½°W., 51½ lks., mkd: T24S R1W S30 BT.

A sawed fir stump, 42" dia., bears N.34¼°W., 81½ lks., mkd: T24S R1W S19 BT.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart - Aug. 12, 1981 - C.S. File 61/27-31

Found - Brass cap (DCSO) protruding 14" out of ground & (properly) marked.

Orig. corner stone (12x8x8") marked with 2 notches on the South face & 5 notches on the East face, leaning against the NE side of the brass cap.

24" Fir (orig. 20") stump, which has been treated & had the bark removed (face no longer recognizable), bears N.73°E., 25.0 ft. (rec. 25.7 ft.)

18" Fir (orig. 16') stump, which has been treated & had bark removed (face no longer recognizable) bears S.41°E., 24.9 ft. (rec. S.45°E., 25.7 ft.)

Note - The orig. 8" Fir & 20" Cedar & 1966's 8" Hemlock have all 3 been taken out by logging.

Unrecorded 29" Fir stump, treated, bark gone & scribed: T24S R1W S30 BT, bears S.73°W., 33.8 ft.

Unrecorded 36" Fir stump, treated, bark gone & scribed: T24S R1W S19 BT, bears N.33°W., 52.7 ft.

Both unrecorded BTs have 1981 BLM BT tags.

New BOs- Set boat spike, stamped BO 1, in top of orig. 20" Fir now 24" stump, bears N.73°E., 25.0 ft.

Set boat spike, stamped BO 2, in top or orig. 16" Fir now 18" stump, bears S.41°E., 24.9 ft.

Set boat spike, stamped BO 3, bears in top of 36" Fir stump, bears S.73°W., 33.8 ft.

Set boat spike, stamped BO 4, bears in top of 36" Fir stump, bears N.33°W., 52.7 ft.

All stumps have DCSO BT tag.