

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; & 5, T25-1

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2778)

-----  
 Set a Hemlock post 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N. face, from which  
     A Fir 36" dia., bears S.74°E., 28 lks. dist. mkd. 1/4 S BT.  
     A Cedar 14" dia., bears N.43°W., 8 lks. dist. mkd. 1/4 S BT.  
 Corner is on a hillside, sloping N. about 100 ft. above creek.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
 Nov. 1966 - C.S. File 52/30-57

-----  
 Found - Orig. 14" now 17" Cedar N.43°W., 5.3 ft. Open and find scribing.  
           Orig. 36" now 40" Fir, S.74°E., 18.5 ft. alive, shows good scar.

Set Brass cap at cor. mkd:           County Surveyors Office  
   T 24 S  
   1/4   S 32  
   S 5  
   T 25 S  
   1966

New BTs- 6" Hemlock N.52°W., 26.7 ft. mkd. 1/4 S32 CS BT.  
           5" Hemlock S.49°E., 32.5 ft. mkd. 1/4 S5 CS BT.

Fd. OK, DCSO, V. Tracy, 1970 C.S. File 54/27-193

Douglas Co. Surveyors Office - Gary L. Langlitz, Frank C. Silagy, crew - May 1, 1978 - C.S. File 60/11-1

-----  
 Found - A 1" x 30" I.P. lying on the ground out of position with brass cap attached as mkd. in 1966.  
         An orig. 14" R.Cedar now a 17" shattered stob, 3 ft. tall scribing "4S" visible on previously opened blaze on downed portion of the tree located down hill from the shattered stump bears N.43°W., 5.3 ft.  
         An orig. 36" D.Fir now 40" and uprooted with well healed blaze stump hole bears approx. S.74°E., 18.5 ft.  
         A 6" now 7" Hemlock, blown down but still alive with scribing "1/4 S32 CS BT" visible on unhealed double blaze, bears N.56 1/2°W., 26.7 ft. (Rec. N.52°W., 26.7 ft.)

(Cont. Next Page)

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; & 5, T25-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 5" now 6" Hemlock, alive with scribing "¼ S5 CS BT" visible on unhealed double blaze, bears S.44½°E., 32.5 ft. (Rec. S.49°E., 32.5 ft.)

At a location which agrees with the measurements listed for the previously described corner accessories, WE RESET the 1966 DCSO brass cap 28" in the ground on a steep N. slope and add the markings "Reset 1978" to the brass cap.

New Accessories:

A boat spike marked "BT 1" set near the heart on top of a 54" S.Pine stump, bears S.87°W., 32.3 ft. Corner is located in cut over area.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed Sept./Nov. 2011 - (DCSO records BLM Plat T25-1W 2012-2 & Vol. 58 Pages 22945-6)

-----  
The ¼ sec. cor. of secs. 5 & 32, on the N bdy. of the Tp., perpetuated by the Douglas Co. Surveyor's Office 1966 & 1978, monumented with an iron post, 1¼" dia., firmly set, flush with the ground surface, with brass cap (properly) mkd from which the remains of the orig. BTs

A roothole bears S.74°E., 18.5 ft. downhill of which is an uprooted fir snag, 51" dia., with no marks visible on a partially healed blaze.

A decayed cedar stump, size indeterminate, bears N.43°W., 5.3 ft. with no marks visible on a partially healed blaze.

and the remains of a BT mkd by Douglas Co. Surveyor's Office in 1966

A split hemlock stump, size indeterminate, bears S.46°E., 32.6 ft. with scribe marks BT visible on an open blaze. and an accessory set by the Douglas Co. Surveyor's Office in 1978

An iron spike, 1/2" square, bears S.86½°W., 32.4 ft., driven flush with the top and near the center of a sawed sugar pine stump, 51" dia., with a convex head mkd. BO-1

and new BTs

A fir, 7" dia., bears S.27°E., 33.7 ft., mkd: ¼ S5 BT.

A hemlock, 11" dia., bears N.85¼°W., 21.7 ft mkd: ¼ S32 BT

Gerald V. Nygren - For: Barnes & Assoc. Inc. - 11/2016 - M172-62

-----  
Found - 1966 C.S. brass cap per rec.  
(1896) 36" Fir, now root hole bears S.74°E., 18.5'  
14" Cedar, now rotten stump bears N.43°W., 5.3', no  
marks visible. continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

(1966) 5" Hemlock, now split stump bears S.46°E., 32.6' healed face  
(1978) 54" S.Pine stump, now 51" with 1/2" square iron spike in top near center bears S.86°30'W., 32.4'  
(2011) 7" Fir, now 8" bears S.27°E., 33.7' visible scribe.  
11" Hemlock, now 12" bears N.85°15'W., 21.7' visible scribe.

Russell Badgley - For: Seneca Jones Timber Co. - 3/2021 - M179-9

-----

Found - A 1" iron post by Tracy, in 1966 & reset by Langlitz in 1978, firmly set & projecting 2" above the ground, with a 2½" brass cap (properly) marked, from which

- A split stump hemlock (1966) bears (S.46°E., 32.6')2016 rec.
- A 51" sugar pine stump (1978) with a 1/2" square iron spike in the top near center bear (S.86°30'W., 32 4')2016 rec
- A 10" D.Fir (2011) bears S.27°15'E., 33.6 ft w/visible scribe (S.27°E., 33.7')2016 rec
- A 14" Hemlock (2011) bears N.85°00'W., 21.7 ft w/visible scribe (N.85°15'W., 21.7 ft) 2016 rec

New BTs- A 15" D.Fir bears S.72°45'E., 36.4 ft scribed "¼ S5 BT" on double blaze

- A 15" Hemlock bears N.42°40'W., 15.6 ft scribed "¼ S32 BT" on double blaze.