

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5, T25-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2778)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground for cor. of 33, 4, 5, and 32, marked T24S S33 on NE.; R1W S4 on SE.; T25S S5 on SW.; and S32 on NW. faces, with 2 notches on W. and 4 notches on E. edges; from which

A Fir 8" dia., bears N.60°E., 8 lks. dist. mkd. T24S R1W S33 BT.

A Fir 24" dia., bears S.10°E., 51 lks. dist. mkd. T25S R1W S4 BT.

A Fir 12" dia., bears S.51½°W., 6 lks. dist. mkd. T25S R1W S5 BT.

A Fir 12" dia., bears N.44°W., 28 lks. dist. mkd. T24S R1W S32 BT.

Cor. is on a hillside, sloping N. about 100 ft. above creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone, crew - Aug. 1962 - C.S. File 52/42-23

Found - New 4" x 4" Cedar stake at corner.
Fir now 34", S.10°E., 33.7 ft., shows 2 good axe scars.

Fir tree, uprooted and down, S.51½°W., 4.0 ft., opened scar and found good scribing "SR".

Fir tree, uprooted and down, N.60°E., 5.3 ft., shows good scar.

Fir tree, uprooted and down, N.44°W., 18.5 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T24S S 32 | S 33 T25S R1W
S 5 | S 4
1962

New BTs- 16" D.Fir S.24°W., 22.9 ft. mkd. T25S R1W S5 CS BT.

11" D.Fir N.20°W., 14.7 ft. mkd. T24S R1W S32 CSBT

8" D.Fir N.45°E., 23.2 ft. mkd. T24S R1W S33 CS BT

Fd. OK, DCSO, V.R. Tracy - May 1970 C.S. File 54/27-193

Fd. OK and used in BLM resurvey by James E. Jelley, Cadastral Surveyor, Group #'s 350 & 929, Surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16339)

continued next page

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5, T25-1

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Russell Badgley - For: Seneca Jones Timber Co. - 3/2021 - M179-9

Found - A 1" iron post by Godfrey, firmly set and projecting 5" above the ground, with a 2½" brass cap (properly) mkd from which
A 19" D.Fir bears S.23°00'W., 22.7 ft w/healed (S.24°W., 22 9') 1962
A 19" D.Fir bears N.20°15'W., 14.4 ft w/healed (N.20°W., 14.7') 1962
A Hemlock snag (D.Fir) 1962, bears N.48°30'E., 24.0 ft w/healed blaze (N.45°E., 23.2') 1962
New BTs- A 17" Cedar bears N.69°45'W., 34.8 ft scribed "T24S R1W S32 BT" on double blaze
A 20" D.Fir bears N.88°45'E , 14.1 ft scribed "T24S R1W S33 BT" on double blaze

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 7/6/2023 - C.S. File 67/56-44

Found ok per M179-9 (3/2021)
Area burnt 9/2020
Area lightly burned, trees found as described in 3/2023
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 220628.759 E 300241.177