

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 33; & 4, T25-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2779)

Set a Hemlock post 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S on N. face, from which
A Yew 12" dia., bears S.82°E., 27 lks. dist. mkd. 1/4 S BT.
A Hemlock 36" dia., bears N.55°W., 17 lks. dist. mkd. 1/4 S BT.
Cor. is on a hillside, sloping W. about 25 ft. above creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone, crew - Sept. 1962 - C.S. File 52/42-28

Found - 14" Yew tree, S.82°E., 17.8 ft. (slope dist.) Both scars previously opened. Good scribing vis. on still solid faces.
36" W.Fir N.55°W., 11.2 ft., broken off about 25 ft. above ground, nearly dead snag. Both scars previously opened and good scribing "1/4 S BT" visible on old face.
Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 1 W
1/4 S 33
S 4
T 25 S
1962
New BT - 8" Hemlock N.12°W., 38.5 ft. mkd. 1/4 S33 CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 3, 1966 - C.S. File 52/30

Found - Orig. 14" Yew, S.82°E., 17.8 ft., scribe visible on unhealed blaze.
36" W.Fir now 25 ft. high snag, N.55°W., 11.2 ft. scribe visible.
No trace of brass cap as recorded in 1962.
Due to logging, Hemlock BT, now knocked over.
Set Brass cap at cor. mkd: County Surveyors Office 1966
T24S 1/4 S 33 R1W
T25S S 4
New BTs- 6" Hemlock S.29°W., 39.9 ft. mkd. 1/4 S4 CS BT.
11" Hemlock N.83°E., 60.4 ft. mkd. 1/4 S33 CS BT.
This corner lies on E-W cutting line cut off to N., approx. 300 ft. E. of small creek, course SW.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 33; & 4, T25-1

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 929, Surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16338)

(Corner Report)

The ¼ sec. cor., perpetuated and recorded by Godfrey in 1962, and further perpetuated by Tracy in 1966, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground with brass cap mkd. in 1966, from which the remains of an original bearing tree:

A Hemlock snag, 40" dia., bears N.55°W., 17 lks. dist. with scribe marks ¼ S33 BT visible on open blaze. and the remains of a bearing tree mkd. by Godfrey:

A root hole bears N.12°W., 58½ lks. dist., with a down Hemlock alongside, 8" dia., with scribe marks ¼ S33 CS BT visible on open blaze.

and the remains of bearing trees mkd. by Tracy:

A sawed Hemlock stump, 11" dia., bears N.83°E., 91 lks. dist., with a down log alongside, with fragmentary scribe marks visible on open blaze.

A root hole bears S.29°W., 60½ lks. dist., with a down Hemlock alongside, 6" dia., with fragmentary scribe marks visible on open blaze.

No suitable trees available within limits.