

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2813)  
-----  
Set a basalt stone 14x12x12" 10" in the ground for ¼ sec. cor. marked ¼ on N face, from which  
    A fir, 10" dia., bears N.46°E., 16 lks., mkd: ¼ S BT.  
    A fir, 8" dia., bears S.25°E., 13 lks., mkd: ¼ S BT.  
This cor. is on a steep hillside, sloping S about 60 ft. below spur.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy- V. Tracy - M. Stone - Sept. 1962 - C.S. File 52/42-27  
-----  
Found - Rock as called for in notes, still firmly set, "¼" marked on north face.  
    15" Fir S.25°E., 9.1 ft. (not 8.6 ft.) shows 2 good axe scars.  
    22" Fir N.46°E., 10. ft. (not 10.6 ft.) shows 2 good axe scars.  
Set - Brass cap alongside orig. rock & mkd:  
    COUNTY SURVEYORS T24S 1W ¼ S27/S34 OFFICE 1962  
Rescribed orig. trees -  
    15" D.Fir S.25°E., 9.1 ft., mkd: ¼ S34 CS BT.  
    22" D.Fir N.46°E., 10.0 ft., mkd: ¼ S27 CS BT.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause; Oct. 28, 1996 - C.S. File 65/9-21  
-----  
Found - 2½" brass cap on a 1½" O.D. iron pipe, protrudes 12" above ground. (DCSO) 1962  
    A 15" x 11" x 8" stone marked "1/4" 4 ft. down hill, southeasterly of BC/IP out of ground.  
    10" now 21" dia. rotted 2 ft. high D.Fir stump with a healed blaze. Bears N.46°E., 10.6 ft. (agrees w/orig rec.) O.B.T.  
    Orig. SE BT not found.  
Set - Orig. stone is placed along southerly edge of BC/IP.  
    6" dia. D.Fir, double blazed and scribed "¼ S34 CS BT" bears S.32½°W., 30.2 ft.  
    9" dia. Hemlock, double blazed and scribed "¼ S34 CS BT" bears S.26°E., 35.2 ft.  
    3" dia. D.Fir, double blazed and scribed "X BT" bears N.50°E., 17.9 ft.  
    6" dia. Chinquapin, double blazed and scribed "¼ S27 CS BT" bears N.70½°W., 28.3 ft.  
Note - Corner lies on a steep southeasterly slope.