

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2818)

Set a fir post, 4 ft. long, & 4" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on N face, from which:
A fir, 36" dia., bears N.52°E., 10 lks., mkd: 1/4 S BT.
A fir, 18" dia., bears S.54°W., 51 lks., mkd: 1/4 S BT.
This cor. is on a hillside, sloping S, about 25 ft. below top of ridge.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy; M. Stone, crew - July/Aug. 1962 - C.S. File 52/42-21

Found - Badly rotted Fir stake lying on ground by corner, some scribing still visible "1/4S" I believe this is orig. stake.
Fir, now 40", N.52°W., not (N.52°E.) 6.6 ft. shows very plain axe scar.
Fir, now 22", S.54°W., 33.7 ft., shows very plain axe scar.
Did not open either tree mentioned above.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T24S R1W
OFFICE 1962 1/4 S 15
S 22
New BTs- 22" D.Fir S.54°W., 33.7 ft., rescribed 1/4 S22 CS BT
7" W.Fir N.5°W., 31.2 ft., mkd: 1/4 S15 CS BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - April 13, 1970 - C.S. File 54/27-209

Found - 1962 CS brass cap & pipe, tipped over the rootwad of orig. NW BT & orig. SW BT, face. down. 1962
7" now 8" W.Fir, alive, N.5°E., 31.2 ft., split with about 1/2 of upper blaze hanging loose with scribe marks, lower scar healed over.
Reset brass cap in proper place.
New BTs- 6" W.Fir S.25°E., 55.1 ft., mkd: "1/4 S22 CS BT"
10" D.Fir N.73°E., 38.6 ft., mkd: "1/4 S15 CS BT"
This corner lies moderate SW slope approx. 100 ft. S. of ridge top.