

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35, WC

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2800)

Set a basalt stone 12x10x8" 9" in the ground for 1/4 sec. cor. marked 1/4 on N face, from which

A cedar, 16" dia., bears N.25°E., 26 lks., mkd: 1/4 S BT.

A cedar, 36" dia., bears S.15°W., 25 lks., mkd: 1/4 S BT.

This cor. is on a hillside, sloping E about 100 ft. above McKinley Creek

Douglas Co. Surveyors Office - Vernon R. Tracy & Crew - ~~Oct./Nov. 1966~~ Dec 8, 1964 - C.S. File 52/42-32

Found - Both BTs & basalt stone 6x8x12", set firmly in the ground marked "1/4"

16" now 24" Cedar N.25°E., 17.2 ft., shows very good scars. Didn't open.

36" now 40" Cedar S.15°W., 16.5 ft., shows faint scar. Didn't open.

Set - No brass cap set at this time as road stakes would take corner out - brass cap will be set at later date.

New BTs- 6" Hemlock N.72°E., 35.7 ft., mkd: 1/4 S26 CS BT

8" Hemlock S.26°W., 81.4 ft., mkd: 1/4 S35 CS BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 1966 - C.S. File 52/42-49

Found - Orig. 16" Cedar, alive, N.25°E., 17.2 ft., shows good scar, sets in edge of fill for new logging road.

6" W.Fir (not Hemlock) N.72°E., 35.7 ft. Alive at foot of fill, scribe visible. 1964

8" Hemlock S.26°W., 81.4 ft. Alive, scribe visible on upper side of road. Actual corner falls in rd.

Set - 3/4" I.R. flush with road & surface & witness corner 70 ft. west.

Brass cap at cor. mkd: County Surveyors T24S R1W
Office Wit. Cor. 1/4 S 26
1966 S 35
70 ft. E to Corner

New BTs- 13" D.Fir N.7°E., 12.6 ft., mkd: WC 1/4 S26 CS BT

18" D.Fir S.1°W., 3.8 ft., mkd: WC 1/4 S35 CS BT

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35, WC

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - April 1970 - C.S. File 54/27-211

Found - Brass cap bent over. BTs burned but still alive - we
straighten cap & rescribe BTs.

Set - 6' steel fence post alongside brass cap - metal
locator indicates I.R. at true cor. point still
in place under road fill.