

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2788-9)

Set Fir post, 3½ ft. long, & 4" sq., 24" in the ground for the ¼ sec. cor. marked ¼ S on N face, from which:
A hemlock, 18" dia., bears S.72°E., 5 lks., mkd: ¼ S BT.
A fir, 20" dia., bears N.40°E., 27 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Terry Connell - June 1965 - C.S. File 52/42-37

Found - Orig. 18", now 22" hemlock S.72°E., 3.3 ft., open & shows "4S" scribe, tree alive.
20" Fir, down & badly rotted N.40°E., 17.8 ft., fragments of old face visible.
Set - Brass cap at cor. mkd: County Surveyors T24S R1W
Office, 1965 ¼ S 24
S 25
New BT - 10" hemlock N.22°E., 54.4 ft., mkd: ¼ S24 CS BT.
Note - This corner lies on steep East slope approx. 230 ft. West of Creek.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause; Oct. 24, 1996 - C.S. File 65/9-22

Found - 2½" dia. DCSO brass cap on a 1½" O.D. iron pipe, protrudes 12" above ground. Note: BC is orientated northwesterly. 1965
18" now 24" dia. Hemlock, with a partially healed previously opened blaze, bears S.85°E., 4.0 ft. (rec. S.72°E., 3.3 ft. bearing hits center of trunk, dist. would fit a face measurement) O.B.T.
20" now down and rotted D.Fir root hole near rec bearing and dist. "N.40°E., 17.8 ft." O.B.T.
10" now 12" dia. Hemlock, with a partially healed double blaze, illegible scribing visible, bears N.22°E., 54.4 ft. (agrees with rec.) 1965
New - 31" dia. Hemlock, double blazed and scribed "¼ S25 CS BT" bears S.85°W., 9.0 ft.
38" dia. D.Fir, double blazed and scribed "¼ S24 CS BT" bears N.16½°W., 54.5 ft.
Note - Corner lies approx. S.60°W., 250 ft. from the intersection of two creeks on an easterly slope.