

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2772)

Set a basalt stone 12x8x8 ins., 8" in the ground, for 1/4 sec. cor. mkd. 1/4 on W. face, from which
A Fir 18" dia., bears N.30°E., 11 lks. dist. mkd. 1/4 S BT.
A Fir 36" dia., bears S.15°W., 16 lks. dist. mkd. 1/4 S BT.
Cor. is on a hillside, sloping SE.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
June 1965 - C.S. File 52/42-33

Found - Orig. 18" now 28" Fir, N.30°E., 7.3 ft., down and out of place, we open and find scribe marks.
Orig. 36" now 37" Fir, S.15°W., 10.6 ft., shows good scar, alive and in good condition.
No trace of rock called for.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S
R1W 1/4 S24 | S19 R1E
1965

Cap is set under root was of NE. BT.
New BT - 22" D.Fir S.78°E., 24.6 ft. mkd. 1/4 S19 CS BT.
Corner is on steep S. slope approx. 300 ft. from foot of hill

Dennis Gaylord, U.S. Forest Service, Deputized by DCSO -
Sept. 9, 1977 - C.s. File 59/40-6

Found - 1965 DCSO brass cap torn out of the ground, properly stamped. While digging to Re-Set brass cap, the orig. corner stone was found buried upside down mkd. "1/4".
Orig. 31" now 36" D.Fir (DBH on high side) bears S.15°W., 10.6 ft. Has a healed blaze and BLM BT sign.
23" D.Fir set in 1965, bears S.82°E., (to base of tree which is leaning slightly downhill) 24.6 ft. Partly healed blaze with scribing visible "S19 BT". Also has BLM BT sign.
The orig. NE. BT is down.
Placed County BT signs on both trees.
Using both the orig. and the 1965 BTs for reference, I RESET the 1965 brass cap and stamp it "1977".
No new accessories.