

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18, T24-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2770)

Set a basalt stone 15x12x8 ins., 12" in the ground for ¼ sec. cor. mkd. ¼ on W. face, from which
 A Fir 36" dia., bears N.25°E., 47 lks. dist. mkd. ¼ S BT.
 A Fir 60" dia., bears S.52°W., 98 lks. dist. mkd. ¼ S BT.
Cor. is on a steep hillside, sloping SE.

Douglas Co. Surveyors Office - Dennis Gaylord, U.S. Forest Service, Deputized by County, Roland Simshauser, crew - May 4, 1978 - C.S. File 60/11-6

Found - After a thorough search, did not find the original corner stone.
 Orig. 36" Fir, is now a 31" snag, 20 ft. high, bears N.25°E., 31.02 ft., open and find scribing "¼ S BT"
 The orig. 60" Fir has fallen and slid downhill approx. 100 ft. No scar visible. Stump hole bears S.52°W., 64.48 ft.
Using the orig. BT snag for reference, I SET a 2½" brass cap on a 1" I.P. at corner point stamped: County Surveyors Office T24S ¼ R1W S13 S18 R1E 1978".
New BTs- 18" D.Fir bears N.34°E., 35.0 ft. scribed "¼ S18 CS BT" on a double blaze.
 12" D.Fir bears N.11°30'W., 16.2 ft. scribed "¼ S13 CS BT" on a double blaze.
Placed County BT signs on two new BTs and on orig. BT snag. Corner falls on a 75% South slope.