

PRIMARY CORNER DESCRIPTION NE. Cor. Section 1 (Tsp Cor)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_


GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2133)

-----  
 Set a post, for cor. to Tps. 23 and 24 S., Rgs. 1E and 1W, 4 ft. long, 4" sq., 24" in the ground, mkd. T23S S31 on NE.; R1E S6 on SE.; T24S S1 on SW.; R1W S36 on NW. faces with 6 notches on N., S., E., and W. edges, from which  
     A Fir 14" dia., bears N.60°E., 27 lks. dist. mkd. T23S R1E S31 BT.  
     A Fir 36" dia., bears S.40°E., 60 lks. dist. mkd. T24S R1E S6 BT.  
     A Fir 40" dia., bears S.34½°W., 47 lks. dist. mkd. T24S R1W S1 BT.  
     A Fir 7" dia., bears N.1°W., 45 lks. dist. mkd. T23S R1W S36 BT.

GLO resurvey by John G. Collins, U.S. Cadastral Engineer; Dan P. Mumbrue, U.S. Surveyor and Theodore Vander Meer, U.S. Transitman, under Special Instructions, dated May 9, 1922 - (DCSO records Vol. 5 Page(s) 2162-63)

-----  
 The old cor. of Tps. 23 and 24 S., Rs. 1 W and 1 E., is a decaying post, mkd. and witnessed as described in the original field notes, except that the bearing tree in sec. 36 is decayed and fallen.

Alongside the post  
 Set an iron post 3 ft. long, 3" dia., 28" in the ground, for cor. of Tps. 23 and 24 S., Rs. 1 W. and 1 E., with brass cap mkd.



from which  
     A Fir 16" dia., bears N.60°E., 27 lks. dist. mkd. T23S R1E S31 BT. (Old BT)  
     A Fir 38" dia., bears S.40°E., 60 lks. dist. mkd. T24S R1E S6 BT. (Old BT)  
     A Fir 40" dia., bears S.34½°W., 47 lks. dist. mkd. T24S R1W S1 BT. (Old BT)  
     A Fir 8" dia., bears N.8°W., 63 lks. dist. mkd. T23S R1W S36 BT. (New BT)

(Cont. Next Page)

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE. Cor. Section 1 (Tsp Cor)

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
April 15, 1970 - C.S. File 54/27-201

-----

Found - 1922 GLO brass cap on 3" I.P., out of ground.  
Orig. 14" now 22" Fir, alive, N.60°E., 17.8 ft.,  
shows good scar, tagged.  
Orig. 36" now 40" Fir, alive, S.40°E., 39.6 ft.,  
shows good scar, tagged.  
Orig. 40" now 46" Fir, alive, S.34½°W., 31.0 ft.,  
shows good scar, tagged.  
1922, 8" Fir, now 8" snag, N.2°W., 41.6 ft. (Rec.  
N.8°W.) scribe visible on unhealed blaze.

Reset GLO brass cap in proper place.  
New BT - 28" D.Fir, North 44.5 ft. mkd. "T23S R1W S36 DCS BT"  
Corner lies approx. 100 ft. W. of access road from China  
Creek on very steep West slope.