

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John McQuinn, Deputy Surveyor, under Contract #466 dated April 1883 - (DCSO recs. Vol. 7 Page(s) 2881)  
-----  
Set cedar post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 on W face, from which:  
A hemlock, 12" dia., bears S.75°E., 52 lks., mkd: 1/4 S BT.  
A hemlock, 10" dia., bears N.72°W., 55 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Aug 1969 - C.S. File 54/27-253  
-----  
Found - Orig. 12" now 15" Hemlock stump, S.75°E., 34.3 ft., scribe marks visible.  
Hole where NW orig. BT should have been.  
Set - Brass cap at cor. mkd: County Surveyors T24S R2W (6' steel fence Office 1/4 S 30|S 29 post alongside) 1969  
New BT - 40" D.Fir N.45°W., 151.6 ft., mkd: "1/4 S30 CS BT" There being no trees in sec. 29, we set: 3/4" I.R. N.70°E., 15.0 ft.  
This corner lies on moderate, changing to steep, northerly slope.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/27/2022 (filed 1/9/2023) - C.S. File 67/55-19  
-----  
Found - 2 1/2" brass cap (properly mkd) on 1" I.D. iron pipe, up 13" add rough stone mound.  
Burnt-broken 46"x2 ft. D.Fir stump N.45°W., 151.6 ft. No marks found.  
6' steel post along side.  
New - 5/8"x30" iron rod with DCS0 yellow plastic cap S.63°E. 13.7 ft., up 6".  
5/8"x30" iron rod with DCS0 yellow plastic cap N.21°W. 15.0 ft, up 12"  
9"x8 ft. burned-sawn fir stump S.30°W., 14.2 ft. 3 1/2" PK nail right side center.  
10"x8 ft. burned-sawn fir stump N.85°W., 13.5 ft. 3 1/2" PK nail right side center.  
Note - Area burnt 9/2020  
Mon. On north edge near top of NW running ridge 20' South of gravel road.  
O CRS state Plane coordinate system  
Cottage Grove - Canyonville Zone  
N. 225961.762  
E. 260634.757