

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Wit Cor Secs 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John McQuinn, Deputy Surveyor, under Contract #466 dated April 1883 - (DCSO recs. Vol. 7 Page(s) 2881-2)

Set a post (yew), 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 19, 20, 29, & 30, marked T24S S20 on NE, R2W S29 on SE, S30 on SW, S19 on NW faces, with 2 notches on S & 5 notches on E edges; from which
 A hemlock, 6" dia., bears N.50°E., 17 lks., mkd: T24S R2W S20 BT.
 A hemlock, 18" dia., bears S.60°E., 40 lks., mkd: T24S R2W S29 BT.
 A hemlock, 18" dia., bears S.70°W., 15 lks., mkd: T24S R2W S30 BT.
 A fir, 36" dia. bears N.50°W., 17 lks mkd: T24S R2W S19 BT

Glen McChesney, Weyerhaeuser - 3/14/1972 - C.S. file 59/24-3

Found - 6" now hemlock 20" stump, scribing visible now pushed out of orig. location by road construction. (Rec. N.50°E., 17 lks. now N.7°W., 70.0 ft.)
 Root hole of down, badly rotted hemlock, but could find no indication of a face. S.60°E., 31.0 ft. to old root hole of possible BT
 18" now 20" down, shattered hemlock, broken off & stump still in place, old face, bears S.60°W. 9.9 ft. (rec. S.70°W.) to center of shattered stump.
 36" fir stump, scribing visible upper face, lower face not opened, bears N.61°W., 11.2 ft. to center of fir stump. (Rec. N.50°W.)
 Fd. in field, 4 references (Plates & "W" nails) Plates removed & new plates put up the new bearings & distances.
Set - ½" Iron pipe, set by dist. & bearing from Identified NW & SW BTs & new bearing recorded.
 44" Fir, S.62°W., 124.7 ft., "W" nail & plate
 40" Fir, S.86°W., 79.3 ft., "W" nail & plate
 48" fir stump, N.49°W., 125.0 ft., "W" nail & plate

Douglas Co. Surveyors Office - Gary L. Langlitz - Karen Cheney - Sept. 22, 1976 - C.S. File 59/24-3

Fd - Orig. NW BT, now stump, situated on top edge of road cut & slid out of orig. position.
 No trace of other orig. evidence.
 40" D.Fir stump with railroad spike in center, bears S.50°W. 40.6 ft (Weyerhaeuser rec. S.50°W., 40.6 ft)
continued next page

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Wit Cor Secs 19, 20, 29, & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

36" Hemlock stump with "W" nail bears S.67°W., 28.3 ft.
44" D.Fir stump with "W" nail bears S.62°W., 124.7 ft.
40" D.Fir stump with "W" nail bears S.86°W., 79.3 ft.
48" D.Fir stump with "W" nail bears N.49°W., 125.0 ft.
We do not find the ½" IP set by Weyerhaeuser Co.

Since this cor. position falls on the road cut bank, We set a witness corner 50' West of the true corner.

Set - 1"x30" I. Pipe, 24" in the ground with brass cap attached mkd: Douglas Co. Surveyor

Wit. Cor.

East 50 ft. to

T24S R2W

S 19 | S 20

S 30 | S 29

1976

from which we note the following bearing objects

The aforementioned railroad spike set in a 36" D.Fir stump bears S.34½°E., 33.6 ft., from the witness corner.

A 5/8"x30" I.Rod driven 16" deep in the center of a 38" Hemlock stump, bears S.36°W., 39.2 ft., with alum. cap attached mkd. "Douglas County Surveyor WC RP2" This stump has been notched for use as a logging anchor.

A bridge spike driven in the center of a 38" D.Fir stump marked "WC RP3" bears N.36°E., 10.6 ft.

Note - This corner is located approx. 50 ft. west of Weyerhaeuser R. #317.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/24/2023 - C.S. File 67/57-9

Found - (WC) DCS0 brass cap (properly mkd)
Burned, rotted 40"x3 ft Fir stump, S.46°W., 83.9 ft. to witness cor (rec S.62°W. 124.7 to true corner)
Burned, rotted 28"x2 ft. D.Fir stump S.79°W., 30.6 ft to witness corner (rec. S.86°W., 79.3 ft to true corner)
36" D.Fir stump with railroad spike in center bears S.35½°E., 33.6 ft. (rec. S.34½°E.)
28"x3 ft. burned, rotted Hemlock stump I.rod and cap loose on ground reset in stump center S.36°W., 39.2 ft.
Very rotted - burned 28"x2 ft. D.Fir stump N.36°E., 10.6 ft. bridge spike gone.

New - 5/8" iron rod's with DCS0 yellow plastic cap up 3" in red painted mound of stone bears East 90.0 ft North 82.0 ft.

Note - Area burnt 9/2020
Compass decl. 14½°E.

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Wit Cor Secs 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner is approx 105 ft± west & 75 ft south of road
Weyco #317
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 228501.090 E 260583.111
Coord. on witness cor. set 50 ft west from true corner.