

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 6

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

| |
|---|
| <p>GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2936)</p> <p>-----</p> <p>Set post, 3 ft. long, & 3" sq., 24" in the ground for the ¼ sec. cor. marked ¼ S on N face, from which: A vine maple, 6" dia., bears N.28°W., 13 lks., mkd: ¼ S BT A hemlock, 16" dia., bears N.12°E., 24 lks., mkd: ¼ S BT.</p> |
| <p>Marion Hale, Weyerhaeuser Co - 3/3/1961 - C.S. File 53/110-1</p> <p>-----</p> <p>Found - 26" Hemlock, N.12°E., 15.8 ft., chopped out & fd. scribing. No trace of 6" Vine Maple, N.28°W., 8.6 ft. Set - Hemlock post for corner, post is against a fir log. 48" Fir S.56°E., 34.6 ft., "W" nail & plate. 50" Fir S.52°W., 104.4 ft., "W" nail & plate.</p> |
| <p>Glen McChesney, Weyerhaeuser Co. - 10/13/1970 - C.S. File 53/110-18</p> <p>-----</p> <p>Found - Orig. 6" Vine Maple, gone. 26" Hemlock scribing visible, bears N.12°E. 15.8 ft 48" Fir uproot stump rolled downhill, S.56°E., 34.6 ft., to root hole. 50" Fir uproot stump tipped over onto plates & partly buried. S.52°W., 104.4 ft., to root hole. New - Drove "W" nail into old fir log at corner point & drove ½"x40" pipe alongside. 26" Hemlock stump (orig.) bears N.12°E., 14.6', "W" nail & plate. 46" Cedar stump S.15°E., 39.8', "W" nail & plate. 50" Cedar stump N.69°E., 38.2', "W" nail & plate.</p> |
| |