

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 7 Page(s) 2870)

-----  
Set post 3" sq., 3 ft. long, 24" in ground for ¼ sec. cor. mkd. ¼ S. on N. face, from which  
A Fir 20" dia., bears N.32°E., 16 lks. dist. mkd. ¼ S BT.  
A Fir 18" dia., bears S.22°W., 11 lks. dist. mkd. ¼ S BT.

BLM resurvey by Levi E. Tallett and C. Albert White, Cadastral Surveyors, under Group #294, Surveyed May 1951/Aug. 1963 - (DCSO records Vol. 32 Page(s) 13280-81)

-----  
"The intermediate corners along this line which were established by McQuinn formerly referred only to T. 24 S., R. 2 W. The purported retracement of the south boundary of sec. 31 and the reported establishment of closing corners on the boundary by Hezekiah Johnson in 1900 **having proved to be fictitious**, the McQuinn corners except for the south ¼ sec. cor. of sec.31 and the south ¼ sec. cor. of sec. 36, are changed in 1963 to corners of maximum control in order to provide a basis for Consent Decree "Civil No. 60-135, Oregon."

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner. This now becomes the ¼ sec. cor. of secs. 4 and 33.

Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap mkd:

¼  $\frac{S\ 33}{S\ 4}$   
1951

from which

A Hemlock 42" dia., bears N.12°W., 42 lks. dist. mkd. ¼ S33 BT. (1951 BT)

A Cedar 14" dia., bears S.33¼°W., 79 lks. dist. mkd. ¼ S4 BT. (1963 BT)

Glen McChesney - For: Weyerhaeuser Co. - July 13, 1976 (Filed Dec. 1980) - C.S. File 58/8-29&30

-----  
Found - 1951-63 GLO brass cap.

42" Hemlock (1951) scribing visible. This tree will be removed by current road construction. Tree bears N.11¼°W., 27.4 ft.

14" Red Cedar (1963) scribing visible bears S.35°W., 52.6 ft. Tree is at westerly edge of R/W but should survive road construction.

(Cont. Next Page)

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 33; & 4, T25-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BRASS CAP TO BE RESET AFTER ROAD CONSTRUCTION.

Accessories added this date:

48" Fir S.49°E., 71.2 ft. with W nail and plate.  
40" Fir S.71°W., 69.0 ft. with W nail and plate.  
38" Fir N.36°W., 72.9 ft. with W nail and plate.

Frank Williams (work done by Glen McChesney) - For:  
Weyerhaeuser Co. - 2/20/1981- C.S. File 58/8-30

-----  
Found - 42" Hemlock N.11¼°W., 27.4 ft. - gone.  
14" Red Cedar S.35°W., 52.6 ft. - gone  
48" Fir stump, S.49°E., 71.2 ft. w/W nail, plate OK  
40" Fir stump, S.71°W., 69.0 ft. w/W nail, plate OK  
38" Fir stump, N.36°W., 72.9 ft. w/W nail, plate  
(stump was burned, W nail intact but plate was  
gone so renewed plate w/same bearing & dist.

BT added Aug. 1978:

54" Fir stump, N.31°W., 50.2 ft. w/W nail & plate.  
Reset - 1951-63 GLO brass cap, 1' under surface of rock  
logging road.  
N.70°W., 43.5' to most easterly point of large  
boulder 15'x15'x20'.