

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2916)

-----

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on N face, from which:  
A hemlock, 5" dia., bears N.60°E., 12 lks., mkd: 1/4 S BT.  
A fir, 16" dia., bears S.20°E., 25 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Aug 1969 - C.S. File 54/27-247

-----

Found - Orig. 16" now 18" fir decayed stump, S.20°E., 16.5 ft., open & find "1/4 S" scribe.  
No trace of other orig. BT  
Weyerhaeuser reference trees now burned stumps.

Set - Brass cap at cor. mkd: County Surveyors T24S R2W  
(6' steel fence post Office 1/4 S 21  
set alongside BC) 1969 S 28

No trees nor solid stumps available, we set:  
3/4"x30" I.Rod, North 10.0 ft.  
3/4"x30" I.Rod, West 20.0 ft. as reference to 1/4 corner  
This corner lies in old clear cut unit in greasewood.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/23/2023 - C.S. File 67/57-7

-----

Found - 2 1/2" DCSO brass cap on 1" I.D. iron pipe up 8" (cap properly mkd)  
3/4" iron rod, North 10.0 ft.  
3/4" iron rod, West 20.0 ft.  
Fence post loose on ground, reset 1.0 ft South

New - 16"x1 1/2 ft. sawn fir stump S.48°W., 7.6 ft. 3 1/2" mag nail top center.  
18"x 1/2 ft. sawn fir stump N.42°W., 7.7 ft. 3 1/2" mag nail top center.

Note - Corner is approx 150 ft. south of gravel road.  
Area burnt 9/2020  
Compass decl. 14 1/2°E.

Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 229608.934 E 268308.686