

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO recs Vol 7 Pg 2914)</p> <p>-----</p> <p>Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on W face, from which: A hemlock, 6" dia., bears N.55°W., 30 lks., mkd: 1/4 S BT. A fir, 16" dia., bears N.52°E., 24 lks., mkd: 1/4 S BT.</p>
<p>V.W. Hosford - Sept. 1957 - C.S. File 42/306-7</p> <p>-----</p> <p>Before logging both BTs were standing. The BT for Sec. 27 was a dead snag. After logging in Sec. 27, the BT for that sec. is a broken stump with scribing visible. The orig. BT for Sec. 28 is in good condition, (now 9" dia.) At the true point of the corner I drove an 1 1/2" iron pipe 30" long 18" in the ground, from which: A fir 38" dia., bears N.76°E., 31.6 ft., mkd: 1/4S 27 253 BT A fir 22" dia., bears S.73°W., 14.5 ft., mkd: 1/4S 28 253 BT</p>
<p>Robert A. Cook - For: Weyerhaeuser Co. - Dec. 2009 - M160-24</p> <p>-----</p> <p>Found - 1 1/2" pipe up 8" on gentle south slope. 42" D.Fir stump N.76°E., 31.6 ft. 24" D.Fir snag S.73°W., 14.5 ft with scribes visible New BTs- 10" D.Fir N.2°W. 9.7 ft. scribed "1/4S28" above "BT". 9" D.Fir N.82°E. 10.5 ft. scribed "1/4S27" above "BT".</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/2/2023 - C.S. File 67/57-1</p> <p>-----</p> <p>Found - 1 1/2" iron pipe, leans N.65°W., 0.8 ft., up 10" Rotted, burned 30"x3 ft. D.Fir stump, N.76°E., 32.3 ft. (rec. 31.6 ft.) - Hosford BT Broken, burned 20"x3 ft stump, S.73°W., 15.0 ft. (rec. 14.5 ft) blaze gone. Hosford BT Sawn, burnt 12"x7 ft D.Fir stump N.8°W., 9.9 ft. (rec. N.2°W., 9.7) Add 3" mag nail right side center, fully healed double blaze. - Cook's BT Sawn, burnt 14"x4" D.Fir stump N.85°E., 10.2 ft. (rec. N.82°E., 10.5 ft.) blaze gone. Add 3" mag nail top center. - Cook's BT New - Plumb up 1 1/2" iron pipe, drove 5/8"x60" iron rod in center of pipe with DCSO 2 1/2" alum. cap up 10" MKD: DOUGLAS COUNTY 1/4 S28 S27 2023 SURVEYORS OFFICE Note - Area burnt 9/2020 Compass decl. 14 1/2°E. Continued next page</p>

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 227314.271
E 270682.652