

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2918)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on W face, from which:
A fir, 60" dia., bears N.10°E., 22 lks., mkd: 1/4 S BT.
A hemlock, 24" dia., bears N.13°W., 40 lks., mkd: 1/4 S BT.

Ken Perkins, Weyerhaeuser - May 26, 1972 - C.S. File 59/24

Found - 60" now 72" fir bears N.8 1/2°E., 11.4 ft., scribing visible.
24" Hemlock now rotten stump, bears N.13°W., 26.4 ft.
New - 48" Fir S.80°W., 7.7 ft., "W" nail & plate.
Added "W" nail & plate to 72" Fir.

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - Mike Thompkins - 9/1/1976 - C.S. File 59/24-2

Found - An orig. 60" D.Fir, now 60" stump, with scribing "1/4S" visible on previously opened blaze. Ring count indicated approx. 80 yrs of growth & 6" increase in diameter.
We do not find any evidence of the orig. NW BT or the orig. corner monument.
At the true corner point as determined by the rec. bearing & dist., N.10°E., 14.5 ft., to the fd. OBT:
Set - 1"x30" iron pipe 26" in the ground with brass cap attached mkd: Douglas County Surveyor T24S R2W
1976 S 16 S 15
1/4

From which we note the following bearing objects:
A "Weyerhaeuser nail" driven in a notch on the face of the orig. BT stump, bears N.10°E., 11.7 ft.
42" D.Fir stump bears S.78°W., 9.0 ft., ("Weyerhaeuser nail" in this stump bears S.82°W., 7.7 ft.)
We also find an unrecorded 3/4"x30" alum. pipe at corner point.
We place it alongside the brass cap.