

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500119

PRIMARY CORNER DESCRIPTION NW Cor. Tract No. 39 (Sec. 35)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13292)

Point for the NW cor. of Tract No. 39, Sec. 35
Set an iron post, 36" long, 2" dia., 28" in the ground, with
brass cap marked:

T 24 S R 2 W
S 34 | S 35
| TR 39
1963

from which

A sugar pine, 9" dia., bears N.34¼°E., 53 lks. mkd: S35 BT
A fir, 15" dia., bears S.39¼°E., 62 lks., mkd: TR39 S35 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - April 1968 - C.S. File 54/27-143

Found - Cadastral bras cap, bent over & buried. Reset in proper place from BTs as follows:
9" now 10" Sugar Pine N.34¼°E., 35.0 ft., alive, scribe visible on partially healed blaze.
15" Fir, now shattered stump S.39¼°E., 40.9 ft., scribe visible.

New BT - 8" D.Fir, S.63°E., 41.8 ft. mkd: TR39 S35 CS BT.
Note - This corner lies approx. 350 ft. N of Twin Cedar Springs Road on section line between sections 34 & 35.

Douglas Co. Surveyors Office - Gregory E. Quibell, Deputy - Teresa Buley - Oct. 14, 1981 - C.S. File 61/29-12

Found - 1963 BLM brass cap, properly mkd., firmly set.
9" now 14" Pine per resurvey bears N.34°E., 34.5 ft., (Rec. 35.0 ft.)
Rotted remains of 15" Fir per resurvey bears S.39°E., 40.9 ft.
8" now 14" Fir, (1968 ren.) bears S.63°E., 41.8 ft. with well healed scar.

New BTs- 6" Fir bears S.54°W., 5.0 ft., scribed "S34 CS BT" in bark.
11" Fir bears S.83°W., 24.8 ft., scribed "S34 CS BT" in double blaze.

Note - Corner lies north of rock Rd. approx. 220 ft.

continued next page

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500119

PRIMARY CORNER DESCRIPTION NW Cor. Tract No. 39 (Sec. 35)

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/2/2022 (Filed 8/11/2022) - C.S. File 67/54-1

Found - 3¼" BLM Brass cap (properly mkd), proj. 6".
Burnt-sawn 24"x2' D.Fir stump S.65°E., 42.0 ft.
(rec. S.63°E., 41.8 ft.) to 3½" PK nail, top
center. 1968
30" Fir stump sawn flush with ground S.54°W., 5.0
ft. 1981
16"x5' rotten broken Fir snag S.83°W., 24.8 ft. 1981
New - Burned dead 22" D.Fir N.27°E., 33.0 ft. stainless
washer "DOUGLAS CO. SURVEYOR" nailed in face, 3½"
PK nail right side center.
Burnt but alive 56" D.Fir N.78°E., 40.5 ft.
stainless washer "DOUGLAS CO. SURVEYOR" nailed in
face, 3½" PK nail right side center.
Burnt sawn 20"x1.5' D.Fir stump S.03½°W., 12.4 ft.
3½" PK nail top-center.

Note - Corner is approx. 220' north of Cobble Creek access
road.
Area burnt 9/2020
See sketch in file.

Lat: 43°26'21.28"N Long: 122°54'47.10"W