

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2902)

Set a basalt stone 10x9x8" 7" in the ground for ¼ sec. cor. marked ¼ on W face, from which

- A pine, 8" dia., bears S.39°E., 42 lks., mkd: ¼ S BT.
- A chinquapin, 5" dia., bears N.56°W., 7 lks., mkd: ¼ S BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13292-3)

The ¼ sec. cor. of secs. 34 & 35, monumented with a basalt stone, 10x9x8"; firmly set, marked ¼ on W face, from which the orig. BTs:

- A chinquapin, 5" dia., bears N.71°W., 7 lks., with blaze rotted out. (In 1951) (Rec. bearing, N.56°W.) This tree has disappeared by 1963
- A pine, 14" dia., bears S.39¼°E., 42 lks., blaze partially healed & has been cut open, with scribe mark 4 visible. (Rec. bearing S.39°E.)

At the corner point

Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap mkd:

¼
S 34 | S 35
1951

from which

- A fir, 15" dia., bears N.10½°W., 146 lks., mkd: ¼ S34 BT. (1963 BT)
- A fir, 14" dia., bears S.83°E., 67 lks., mkd: ¼ S35 BT. (1951 BT, 20" dia., with blaze healed in 1963)

Bury the orig. corner stone alongside the iron post.

FD BC & 2 BTs, D. Edwards 5/2008 - M156-7

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/18/2025 - C.S. File 67/61-55

No monuments found due to cut bank sliding away.

Found - Burned, dead 27" D. Fir N.10½°W. 79.2 ft. (Rec. 146 lks. 96.4 ft.) fully healed single blaze.

- Burned, dead 27" D. Fir S.83°E. 44.2 ft. fully healed single blaze.

Galvanized steel post is set 1 ft. North of monument.

Continued next page

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set - 5/8"x30" Iron rod with 1 1/2" Douglas County Surveyor aluminum cap protruding 8" above ground. Mon location determined by GPS survey tying into M156-7. This position agrees with record bearing and distance to S.E. bearing tree. Bearing to N.W. tree agrees with record. The distance appears to be erroneous.

New BTS bearing and distance by GPS

5/8"x60" iron rod with D.C.S.O. yellow plastic cap S.15°07'24"W. 60.8 ft proj. 10".

5/8"x60" iron rod with D.C.S.O. yellow plastic cap S.86°52'51"W., 60.8 ft. proj 10"

Both iron rod are in narrow West shoulder of gravel of road.

Notes - Area burnt 9/2020

Corner monument is near top of steep cutbank on East side of gravel road. Burned old growth to East. Large recent clearcut to West.

Compass decl. 14 3/4°E.

OCRS COORDINATE SYSTEM

COTTAGE GROVE-CANYONVILLE ZONE

N. 222117.831

E.275937.760