

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2903)</p> <p>-----</p> <p>Set a basalt stone, 18x7x5 ins., 12 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; from which A laurel, 7" dia., bears N.67°W., 25 lks., mkd: ¼ S BT. A chinquapin, 8" dia., bears N.30°E., 13 lks., mkd: ¼ S BT</p>
<p>V.W. Hosford - April 1952 - M 12-55</p> <p>-----</p> <p>Found - Orig. marked stone monument. Both BTs dead &amp; rotted. Re-established corner - 1½" IP 16" Fir, mkd: ¼ S27 PS 253 BT, bears N.29°W. 28.0 ft 20" Fir, mkd: ¼ S26 PS 253 BT, bears N.33°E. 46.0 ft</p>
<p>Douglas Co. Surveyors Office - John Powell - W. Penley &amp; J. Heritage - Aug. 1970 - C.S. File 54/27-232</p> <p>-----</p> <p>Found - 16" now 24" D.Fir N.33°E., 46.0 ft., faces badly burnt, scribe legible "¼S" other marks not legible. No trace of NW BT or corner stone due to skid rd (1952)</p> <p>Set - Brass cap at cor. mkd: County Surveyors T24S R2W Office, 1970 ¼ S27 S 26</p> <p>New BT - 13" Cedar, S.70°W., 47.9 ft., mkd: "¼ S27 CS BT" Reblazed &amp; scribed: 24" D.Fir N.33°E., 46.0 ft., mkd: "¼ S26 CS BT"</p>
<p>Douglas Co. Surveyors Office - Gregory E. Quibell, Deputy - Teresa Buley - Oct. 14, 1981 - C.S. File 61/27-11</p> <p>-----</p> <p>Found - 1970 county brass cap, properly mkd, firmly set. 20" now 26" Fir (1952) bears N.33°E. 46.0 ft w/ orig face still showing but burned over. Fd. visible scribing "¼ S26 CS BT" from 1970 along side. 13" Cedar (1070) down &amp; at approx. orig. location. Unable to locate root hole or stump. Scribed "¼ S27 CS BT" visible on tree.</p> <p>New BTs- 18" Fir bears N.3°E., 30.0 ft. scribed "¼ S26 CS BT" in double blaze. 14" Fir bears N.47°E., 38.7 ft. scribed "¼ S26 CS BT" in double blaze.</p>
<p>1</p>