

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 7 Page(s) 2905)

Set a basalt stone 12x12x10" 8" in the ground for ¼ sec. cor. marked ¼ on W face, from which

- A fir, 36" dia., bears N.48°E., 14 lks., mkd: ¼ S BT.
- A fir, 5" dia., bears S.64°W., 19 lks., mkd: ¼ S BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/306-2

Before logging, the orig. stone corner could not be found. There was evidence of an old rotted stump in the correct position of BT for Sec. 22. The BT for Sec. 23 was a dead snag with scribing visible.

After logging in Sec. 22 only the BT for Sec. 23 remains. At the true point of the corner, I drove a 1½" iron pipe 36" long, 24" in the ground, from which:

- A hemlock, 10" dia., bears N.57°E., 3.2 ft., mkd: ¼S 23 253 BT.
- A hemlock, 12" dia., bears N.20°W., 22.5 ft., mkd: ¼S 22 253 BT.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1624, surveyed Aug./Oct. 1991 - (DCSO records Vol. 51 Page(s) 19241-2)

The ¼ sec. cor. of secs. 22 & 23, perpetuated & recorded by Hosford, in 1957, monumented with an iron pipe, 1½" dia., firmly set, projecting 12" above ground, from which the remains of an original BT:

- A fir snag, 42" dia., bears N.48°E., 16 lks., with healed double blaze. (Record, 14 lks.)

and the bearing trees mkd. by Hosford

- A hemlock, 17" dia. bears N.61°E. 5 lks. with healed blaze
- A hemlock, 19" dia., bears N.20¾° W., 35 lks., with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, directly over the 1½" dia. iron pipe, with brass cap mkd.

T24S R2W
 1/4
 S 22 | S 23
 1991

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

continued next page

1

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 2/10/2026 - C.S. File 67/62-12

-
- Found - BLM brass cap on iron pipe up 3".
Rotted 28" x 40 ft. fir snag N.48°E. 10.6 ft. no blaze visible.
22" hemlock N.61°E. 3.5 ft. fully healed single blaze. Add 3½" mag nail right side center.
26" x 10 ft. shattered hemlock stump N.20¾°W. 23.1 ft. fully healed single blaze.
 - New - 16" hemlock S.20°W. 5.3 ft. scribed "¼ S22 BT" on single blaze. Add 3½" mag nail right side center.
26" x 3 ft. hemlock stump S.77°W. 17.0 ft. with 3½" mag nail top center.
 - Notes - Mon. is approx. 220 ft. East of logging spur.
Area burnt 9/2020
Mon. on moderate steep E.N.E. slope on West edge of old growth large clearcut to West.

Compass decl. 14¾°E.
TRIMBLE GEO XT POSITION
43°.47041713 N.
122°.91237684 W.