

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 700372

PRIMARY CORNER DESCRIPTION C C for Secs. 18 & 19, T24-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2852)

At point of intersection (7.54 chs. S.4°29'E. of cor. of secs. 13 and 24, T24-2) I Set a basalt stone 16x10x10 ins., 12" in the ground for closing corner of secs. 18 and 19, mkd. CC on E. face with 3 grooves on N. and S. face, from which
A Cedar 6" dia., bears N.4°E., 137 lks. dist. mkd. T24S R1W S18 BT.
A Fir 20" dia., bears N.88°E., 103 lks. dist. mkd. T24S R1W S19 BT.
This cor. lies on the right bank of Rock Creek.

Survey by Bruce A. Shaner - For: Evans Products Co. - April/May 1965 - M 29-65

I chiseled "X" on rock cliff at westerly side of Rock Creek, from which
12" Cedar, orig. BT, with old faces, bears N.4°E., 90.4 ft.
36" D.Fir snag, orig. BT, with old face, bears N.88°E., 68.0 ft.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug. 1966 - C.S. File 52/42-43

Found - Orig. 36" Fir N.88°E., 68.0 ft., shows scar. Do not open.
"X" on rock face, as recorded by Shaner, now buried. NE. BT, gone.
Set Brass cap at cor. mkd: County Surveyors Office
T24S R2W | S 18 R1W CC
 | S 19
 1966
New BT - 16" D.Fir S.30°E., 24.3 ft. mkd. CC T24S R1W S19 CS BT.
No good trees to NE. except across canyon.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew March 27, 1968 - C.S. File 52/42-60

Found - Orig. 36" D.Fir, now snag, N.88°E., 68.0 ft., shows good scar.
16" D.Fir, now down, S.30°E., 24.3 ft., scribe visible and other marks.
(Cont. Next Page)

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 700372

PRIMARY CORNER DESCRIPTION C C for Secs. 18 & 19, T24-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1966 brass cap, now buried under about 8 ft. of fill.
Area covered with logs to be yarded in a week. Do not set new brass cap as it would certainly be destroyed.
Set 3/4" Iron rod at corner.
New BTs- 26" D.Fir S.35°E, 36.5 ft. mkd. T24S R1W S19 CC CS BT.
12" Cedar S.8½°E., 38.3 ft. mkd. T24S R1W S19 CC CS BT.
No trees available to the North, clear cut unit.
This corner lies approx. 50 ft. West of creek.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - June 8, 2020 - C.S. File 67/49-5

Found - The ¾" iron rod by Tracy was searched for with a magnetic locator and not found, possibly buried by a slide.
At the original corner position perpetuated by in 1968.
Set - A 5/8"x 60" iron rod projecting 12" above the ground in a 18" diam. x 12" high mound of stone with a 1¼" yellow plastic cap marked "DOUG CO. SURVEYOR"
Original BTs by Nicklin in 1896 - No evidence remaining
BTs by Tracy in 1966 - No evidence remaining
BTs by Tracy in 1968 -
A 44" diam. D.Fir bears S.35°E., 36.5 ft with a healed blaze.
A 22" diam. R.Cedar bears S.8½°E., 38.3 ft with no blaze evident.
New - A 6" diam. R.Cedar bears N.50°E., 14.3 ft scribed "X" & "BT" on a double blaze.
A Fir post set by Lone Rock Timber Co. bears North 1.9 ft
Note - The corner falls on a steep east slope on the Westerly bank of Rock Creek at the base of a repaired slide in mixed timber approximately 200 ft East of Rock Creek Rd and 40 ft West of Rock Creek.
All BTs have BT tags attached. All new BTs have double blazed faces with bearing measured to the center of the tree at the root crown and distances measured to a 4" magnetic nail in the side and center of the root crown.
Compass declination: 14 3/4°E.

Fd 5/8" IR as per rec.12/2023 D.Saily - C.S. 65/112-5