

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2966)

-----  
Set Fir post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which  
A Cedar 12" dia., bears N.81°E., 16 lks. dist. mkd. ¼ S BT  
A Hemlock 10" dia., bears S.75°W., 32 lks. dist. mkd. ¼ S BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #658 dated May 21, 1896 (DCSO records Vol. 7 Page(s) 3075)

-----  
We kept a careful watch for the ¼ sec. cor. or its bearing trees, but could not find any indications.

BLM Resurvey by Norman D. Price, Cadastral Engineer, under Group #242, Surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11467)

-----  
Point for the ¼ sec. cor. of sec. 18, T24S R3W., at midpoint on the W. bdy. of sec. 18.  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap mkd. ¼ S 18  
1950  
from which  
A Fir 22" dia., bears N.43¼°E., 116 lks. dist. mkd. ¼ S18 BT.  
A Fir 22" dia., bears S.19°E., 58 lks. dist. mkd. ¼ S18 BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone - June 12, 1963 - C.S. File 53/9-100

-----  
Found - Iron pipe with GLO brass cap set in 1950, in good condition.  
22" Fir S.19°E., 38.3 ft. is alive and in good condition.  
Sawed stump of 22" Fir N.43¼°E., 76.6 ft., scribe visible.  
New BT - 6" W.Fir N.52°E., 26.9 ft. mkd. ¼ S18 CS BT.

Survey by Ronald Geisler - For: Champion International Co. - Oct. 9, 1985 - C.S. File 63/22-7

-----  
Found - 1950 BLM brass cap on a 1" I.P. extends 14" above ground.  
28" rotted Fir stump bears N.43¼°E., 76.3 ft. (Rec. 76.6 ft.), scribing visible.

(Cont. Next Page)

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

34" Fir bears S.19°E., 38.28 ft., closed face.  
New BT - 17" W.Fir bears N.52°E., 26.9 ft. scribed "¼ S18  
BT". This tree had a 1963 BLM tag (BT) on it but  
no face.  
Corner located along N-S wire fence.

BLM resurvey by George M. Winter, Cadastral Surveyor under  
Group No. 2656, surveyed Sept./Nov. 2012 - (DCSO records Vol.  
58 Page(s) 23003)

-----  
The ¼ sec. cor. of sec. 18 only, on the W. bdy. of T24S,  
R3W., perpetuated by Godfrey, in 1963, further perpetuated by  
Geisler, in 1985, monumented with an iron post, 1" dia.,  
firmly set, projecting 10" above ground, with brass cap  
(properly) mkd.

from which the remains of bearing trees mkd. by Price in 1950  
A sawed, decayed fir stump, 21" dia., bears N.43¼°E., 76.6  
ft., with no marks visible.

A fir, 39" dia., bears S.19°E., 38.3 ft., with a healed  
blaze.

and a bearing tree mkd. by Godfrey (also called for as a new  
bearing tree by Geisler)

A fir, 26" dia., bears N.51½°E., 26.9 ft., with a healed  
double blaze.

Corner is located in a fence extending N. and S.

NAD 1983 (2011)

Latitude: 43°28'55.93" N.      Longitude: 123°06'30.35" W.