

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 3010)</p> <p>-----</p> <p>Set cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which A chinquapin, 12" dia., bears N.37°W., 55 lks. mkd: ¼ S BT A fir, 20" dia., bears S.17°E., 64 lks., mkd: ¼ S BT.</p>
<p>BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11486)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 18 & 19, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:</p> <p style="text-align: center;">¼ <u>S 18</u> <u>S 19</u> 1950</p> <p>from which A hemlock, 9" dia., bears N.39°E., 28 lks., mkd: ¼ S18 BT. A hemlock, 24" dia., bears S.25½°W., 64 lks. mkd: ¼ S19 BT</p>
<p>Fd. Ok by R. Geisler, 10/9/1985 - C.S. File 63/22-5</p>
<p>Keith R. Jehnke - 6/15/2005 - C.S. File 65/54-24</p> <p>-----</p> <p>Found - 23" Hemlock stump w/yellow metal location poster bears N.37°20'20"E., 25.1'. (Note: Champion International Corp. posted an additional yellow metal location poster which reads "S.39°W., 25.1' to S¼" 9/1985</p> <p>34" Hemlock partially healed scribe & yellow metal location poster bears S.24°30'30"W., 42.2'</p> <p>Set - 5/8"x30" iron rod w/yellow plastic cap inscribed "AKS ENGR" for north ¼ sec. 19. Steel post was set 0.2' south of monument.</p> <p>Procedure - Rec. dist. of 42.2' (64 lks) was held per dependent resurvey by Norman D. Price, June/July 1950. Rec. dist. of 25.1' was held per Champion International Cor., LS 1988, 9/1985</p> <p>New BO - 5/8"x30" iron rod w/red plastic cap inscribed "AKS ENGR" for witness monument, bears N.17°03'42"W., 15.36' from north ¼ sec. 19.</p> <p>Note - Rec. BT 9" Hem. distance of 28 links was fd. inaccurate. Discrepancy was fd. by Champion International Corp. & corrected in field.</p>
<p>1</p>