

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2958)</p> <p>-----</p> <p>Set ¼ sec. post from which A cedar, 24" dia., bears N.40°W., 8 lks. A fir, 8" dia., bears S.85°E., 22 lks.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - April 1968 - C.S. File 54/27-219</p> <p>-----</p> <p>Reported as not found Logged & burned.</p>
<p>Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121-58 A&B</p> <p>-----</p> <p>Set- 1¼"X36" Iron pipe with brass cap dated 1994 13" fir, S.4°E. 28.9', scribed "¼ S29 BT" 12" fir, S.76°W. 14.6', scribed "¼ S30 BT" 9" fir, N.78°E. 2.8', scribed "¼ S29 BT" 16" fir, N.26°W. 8', scribed "¼ S30 BT" 6' Fencepost 1' north.</p>
<p>FD. Ok by R. Ward, 12/2001 - M 139-34</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 6/14/2016 (Filed 3/17/2020) - C.S. File 67/46-20</p> <p>-----</p> <p>Found - A 1" i.d. iron pipe set at proportionate distance by Baker in 1994, with a 2½" brass cap projecting 4" above a 8" diameter concrete collar marked:</p> <p style="text-align: center;">T24S R3W S30 S29 ¼ PLS 1978 1994</p> <p>BTs by Baker in 1994 - A 10"x12' tall D.Fir bears N.74°E., 2.8 ft. with a healed blaze (Rec. N.78°E.) A root hole bears S.4°E., 28.9 ft. with an uprooted 15" D.Fir alongside with a healed blaze. A 16" D.Fir bears S.67½°W., 15.3 ft. with a healed blaze. A 22" D.Fir bears N.26°W., 8.6 ft. with a healed blaze. (Rec. 8.0 ft.) A Carsonite fence post bears North 1 ft.</p> <p>New BTs- A 25" D.Fir bears S.4°W., 37.0 ft. scribed "¼ S30" "CS BT"</p> <p>continued next page</p>

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Note - All bearing trees have BT tags attached. All new bearing trees have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

Monument falls in a recent clear-cut on a steep easterly slope approximately 25 ft. east of the center of a gravel access road and approximately 10 ft. lower than the surface of the road.

Compass decl. 15°E.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/26/2021 (Filed 11/23/2021) - C.S. File 67/51-22

Condition report

Found - 2½" brass cap on 1" I.D. iron pipe by Baker 1994
A 10"x12' D.Fir (dead snag) N.74°E., 2.8 ft. healed blaze. 1994

A root hole S.4°E., 28.9 ft. uprooted 15" D.Fir alongside with healed blaze. 1994

18" D.Fir S.67½°W., 15.3 ft. healed blaze. 1994

A 24" D.Fir N.26°W., 8.6 ft. healed blaze. 1994

Carsonite post 1' North. 1994

27" D.Fir S.4°W., 37.0 ft. scribes visible. 2016

Note - Corner is approx. 25' east of gravel road & 10' lower.

Area burnt in Archie Cr Fire 9/2020

Compass decl. 15°E.

Lat: 43°27'15.86" N Long: 123°05'22.45" W