

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2958)

-
- Set post cor. to secs. 19, 20, 29, & 30 from which
- A hemlock, 5" dia., bears N.40°E., 26 lks.
 - A maple, 16" dia., bears S.75°E., 18 lks.
 - A cedar, 14" dia., bears S.75°W., 14 lks.
 - A hemlock, 8" dia., bears N.42°W., 42 lks.

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 3007)

-
- The cor. to secs. 19, 20, 29, & 30 having been destroyed by fire, I run north bet. secs. 29 & 30 following the old blazed line & at 80 chs. from the corner to secs. 29, 30, 31, & 32, marked a hemlock, 24" dia, for cor. to secs. 19, 20, 29, & 30, T24S S20 on NE, R3W S29 on SE, S30 on SW & S19 on NW faces, from which
- A hemlock, 12" dia., bears N.69°E., 36 lks., mkd: T24S R3W S20 BT.
 - A hemlock, 4" dia., bears S.44°E., 23 lks., mkd: T24S R3W S29 BT.
 - A hemlock, 14" dia., bears S.46°W., 45 lks., mkd: T24S R3W S30 BT.
 - A hemlock, 14" dia., bears N.59°W., 28 lks., mkd: T24S R3W S19 BT.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Witnesses: Ed Stearns, Chas. Jewell & Roy Abeen - Aug. 11, 1928 - C.S. File 14/65

-
- Location identified from trees described in the notes of the Public Survey Office as set by Wheeler in 1883. All orig. hemlock trees killed & badly rotted.
- Drove Cedar post in center of old hemlock stump (rotted) scribed T24S S20 on NE face, R3W S19 on NW face, S29 CS on SE face & S30 on SW face & set new BTs as follows:
- 24" Hemlock bears S.57°E., 109 lks., blazed & scribed T24S R3W S20 CS BT.
 - 36" Cedar, bears N.80°W., 179 lks., blazed & scribed T24S R3W S19 CS BT.
 - 30" Fir, bears S.15°E., 161 lks., blazed & scribed T24S R3W S29 CS BT.
 - 24" Fir bears S.37°W., 164 lks., blazed & scribed T24S R3W S30 CS BT.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11482)

 The cor. of secs. 19, 20, 29, & 30, remonumented by the county surveyor in 1928. When the orig. corner monumentation was intact, with a cedar post, 3½ ft. long, 5" sq., firmly drove in the center of a decayed stump of the orig. hemlock corner tree, mkd: T 24 S 20 on NE., S 29 CS on SE., S 30 on SW & R3W S 19 on NW face, with 5 notches on E & 2 notches on S edge; from which I find only the remaining BTs mkd. by the County surveyor as follows:

A sawed fir stump, 32" dia., bears S.10½°E., 125 lks., on which the scribe marks BT remain.

A fir, 32" dia., bears S.37°W., 161 lks., mkd. on bark T24S R3W S30 & mkd. BT on almost healed blaze.

A cedar, 40" dia., bears N.75¼°W., 177 lks., mkd: T24S R3W S19 CS BT.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T24S R3W
S 19|S 20
 S 30|S 29

1950

from which

A fir, 6" dia. bears N.45½°E. 13 lks. mkd: T24S R3W S20 BT

A fir, 6" dia. bears S.52°E., 44 lks. mkd: T24S R3W S29 BT

Reset the County Surveyor's wooden post inverted & alongside the iron post.

Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121- 58 A&B

- Found - GLO Brass cap dated 1950
 44" Cedar, N.80°W. 118.1', rec. N.80°W. 179 lks., 1928 Do. Co.
 Rotten stump, S.37°W. 108.2', visible scribing, rec. S.37°W. 164 lks. - 1928 Do. Co.
 Rotten stump S.15°E. 106.3', visible scribing, rec. S.15°E 161 lks. - 1928 Do. Co.
 16" Fir, N.48°E. 8.8', closed face, rec. N.45½°E. 13 lks., 1950 GLO.
 15" Fir, S.47°E 28.9', closed face, rec. S.52°E. 44 lks., 1950 GLO.
 New - 11" Fir, S.18°W. 13.4', to "W" nail, scribed "T24S R3W S30 BT"
 23" Fir, N.62°W. 10.1', to "W" nail, scribed "T24S R3W S19 BT"
 6' fencepost 1' North