

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2959)

-----

Set ¼ sec. post from which  
 A cedar, 8" dia., bears N.20°W., 8 lks.  
 A dogwood, 5" dia., bears South., 9 lks.

---

Douglas Co. Surveyors Office - C.E. Roberts, Co. Surveyor - May 26, 1903 - FB 7 Pg. 7

-----

Set quar. post  
 Fir 3 N.2½°E., 13 (lks. ?)  
 Fir 6 S.65°E., 5 (lks. ?)

---

Douglas Co. Surveyors Office - Arthur Boyer, Deputy - Wit: Ted Shellabarger, Almon Cook, & Walter Cook - 10/17/1938 - C.S. File 31/69

-----

Set from orig. Cedar BT stump & orig. dogwood stump both of which are correct for bearing & dist. from sec. cor. ½ mi. E & are also correct for spacing grub (Dogwood) is growing out of dogwood stump (orig.)  
 Remark Cedar stump & marked New BT  
 8" Fir bears N.83°W., 13.0 ft.  
 6" Fir bears S.47°W., 15.3 ft.

---

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11481)

-----

The ¼ sec. cor. of secs. 20 & 29, remonumented by the County Surveyor with an unmarked iron bar, 3 ft. long, 1¼" sq.; form which the remains of the orig. BTs:  
 A sawed cedar stump, 42" bears N.31°W., 8 lks., mkd. by the County Surveyor ¼ S20 T24S R3W CS BT. (Rec. N.20°W., 8 lks.)  
 A dogwood stool, bears S.14°E., 9 lks., on which no marks remain. (Rec. South, 9 lks.)  
 and new BTs mkd. by the County Surveyor:  
 A fir, 12" dia., bears N.84½°W., 21 lks. with blaze healed  
 A fir, 12" dia., bears S.46°W., 23 lks. with blaze healed  
 At the corner point  
 Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked: ¼  $\frac{S\ 20}{S\ 29}$   
 1950

from which  
 continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 14" dia., bears N.76½°W., 37 lks., mkd: ¼ S29 BT.  
(error in rec. should be S 20)  
Reset the County Surveyor's iron bar alongside the iron post.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - April 1968 - C.S. File 54/27-218

Found - 1950 GLO brass cap, properly mkd. & 1¼ iron bar.  
12" Fir, now high stump, S.46°W., 15.2 ft., shows scar, badly burned.

All other BTs gone, completely.

New BT - 5" Cedar S.24°E., 75.7 ft. mkd: ¼ S29 CS BT.

No other trees available.

Note - Corner lies at end of old E-W fence, running E to Co. Rd. about 550 ft. E edge of red brick chimney on house N.21½°E., 300 ft.

Put line tag on N end of bridge #19/15.3 west side of Co. Rd.

Fd. Ok 6/1991 by D.Peel - M113-43

Fd. OK 10/1989 by L.Dolan - M109-1

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Sept. 17, 1991 - C.S. File 64/17-5

Found - 2½" dia., GLO brass cap on 1" O.D. iron pipe, protruding 12" above ground. (1950 BLM)  
1" sq. x 24½" long iron bar is fd. loose on top of ground near BC/IP. Land owner pulled bar out of ground)

5" now 7" dia., Cedar with a fully healed double blaze, bears S.19°E., 75.7 ft. (rec. S.24°E., 75.7 ft.) (fence attracts compass needle bearing taken away from fence)

Red brick chimney bears N.26½°E., (Rec. N.21½°E.) (see bearing problem above)

No other accessories fd.

New BTs- 11" dia., D.Fir double blazed & scribed "¼ S20 CS BT" bears N.80½°W., 55.8 ft.

23" dia., D.Fir single blazed & scribed "¼ S20 CS BT" N.49°E., 92.4 ft.

5" dia., Ash double blazed & scribed "XBT" bears S.63½°E., 7.8 ft.

Corner lies in an E-W fence line.

Fd. Ok 12/15/94 - M121-58 A & B

Fd. ok by D. Baker, 6/1996 - M 125-33

Fd. BC & 1 BT by R. Cook, 8/2009 - M159-67

Fd. BC by D. Collier 6/2016 - M172-42