

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32, T23-3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol 5 Pg 2212)

Set a Post 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 on N. face, from which

A Dogwood 8" dia., bears N.30°E., 25 lks. mkd. 1/4 S BT.

A Spruce 30" dia., bears S.30°E., 20 lks. mkd. 1/4 S BT.

BLM resurvey by Norman D. Price, Cadastral engineer, under Group #242, Surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11460)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

$$\frac{1}{4} \frac{S \ 32}{S \ 5}$$

1950

from which

A Fir 42" dia., bears N.29°45'E., 27 lks., mkd. 1/4 S32 BT.

A Fir 34" dia., bears S.1°W., 131 lks. mkd. 1/4 S5 BT.

Marion Hale - For: Weyerhaeuser Co- Nov 1958- C.S. 53/111-11

Found - 1950 iron pipe and brass cap, OK

42" Fir N.29°45'E., 27 lks. (17.8 ft.) OK

34" Fir S.1°W., 131 lks. (86.5 ft.) OK

(1946 WT Co. 6 ft. North of Dep. Res. brass cap, destroyed)

Accessories added this date: (1958)

52" Fir N.27°W., 30.3 ft. with "W" nail and plate.

48" Fir stump S.14°E., 33.2 ft. with "W" nail & plate.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1739, surveyed July/Oct.1994 1995 - (DCSO records Vol. 52 Page(s) 20057-8)

The 1/4 sec. cor. of secs. 5 and 32, monumented with an iron post, 1 in. diam., firmly set, projecting 2" above ground, with brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Price

A sawed fir stump, 53" diam., bears N.29 3/4°E., 27 lks., with scribe marks 1/4 S32 visible on opened blaze.

A sawed fir stump, 45" diam., bears S.1°W., 131 lks., with scribe marks 1/4 S5 visible on opened blaze.

and the remains of trees referenced by person(s) unknown
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32, T23-3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A sawed fir stump, 54" diam., bears N.26¼°W., 48 lks., with "W" nail driven in at base.

A sawed fir stump, 53" diam., bears S.14¼°E., 52 lks. with "W" nail driven in at base.

and new bearing trees

A fir, 20" diam., bears N.2½°E., 3 lks., mkd. ¼ S32 BT.

A fir, 15" diam., bears S.58½°E., 24 lks., mkd. ¼ S5 BT.

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, Group No. 2500 Admin file No. 1408, surveyed July/Aug. 2014 - (DCSO records Plat T24-3-2016-1 all info on plat & Vol. 58 Page(s) 23321-2

The ¼ sec. cor. of secs. 5 & 32, on the N. bdy. of the Tp., monumented with an iron post, 1" dia., firmly set, projecting 3" above the ground, with a brass cap (properly) mkd. from which the remains of BTs mkd. by Price in 1950 and reported by Seibold and Browning in 1994

A sawed, decayed fir stump, 48" dia, bears N.29¾°E., 17.8 ft. with scribe marks ¼ S32 visible on an opened blaze.

A sawed, decayed fir stump, 30" dia, bears S.1½°E., 86.5 ft., with no marks visible. (Record, S.1°W.)

and remains of reference trees mkd. by Hale, PLS No. 243, in 1958, reported as by person(s) unknown by Seibold and Browning in 1994

A decayed fir stump, 52" dia, bears S.14¾°E., 34.3 ft., with no marks visible.

A decayed fir stump, 48" dia, bears N.26¼°W., 31.7 ft., with no marks visible.

and new bearing trees

A fir, 20" dia, bears S.34½°W., 19.3 ft., mkd. ¼ S5 BT.

A fir, 7" dia, bears N.42½°W., 32.8 ft., mkd. ¼ S32 BT.

(Note: The bearing trees mkd. by Seibold and Browning in 1994, are now downed and their original positions could not be determined.)

NAD 1983 (2011)

Latitude 43°31'05.10"N

Longitude 123°04'39.61"W