

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 7 Page(s) 2999)

Set hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which
A hemlock, 10" dia., bears N.5°E., 11 lks., mkd: ¼ S BT.
A hemlock, 24" dia., bears S.15°W., 18 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy -9/1967 - C.S. File 54/27

Reported as not found.
Corner probably destroyed by old logging.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 11/14/2023 - C.S. File 67/57-20

Search for using GIS and GPS information.
Find evidence of old logging-skid road.
No hemlock stumps in area.