

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

<p>GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCS0 records Vol. 7 Page(s) 2993)</p> <p>-----</p> <p>Set dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which</p> <p>    A fir, 24" dia., bears N.64°E., 18 lks., mkd: ¼ S BT.</p> <p>    A cedar, 10" dia., bears S.31°W., 13 lks., mkd: ¼ S BT.</p>	
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/27-148</p> <p>-----</p> <p>Reported as not found.</p> <p>Logged &amp; burned many yrs ago, dense brush.</p>	
<p>Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Debby Stewart - March 18, 1981 - C.S. File 61/19-14</p> <p>-----</p> <p>Found - At corner location I found a fairly new 2" x4' limb 6" in the ground "¼ secs. 34" was written on south face. Lying on the ground nearby was a 4" sq. by 4' wood post with axe marks. (Unrecorded Weyerhaeuser renewal)</p> <p>    36" stump of orig. 24" fir, N.64°E., 11.9 ft. Fragments of scribed 4 S are visible on opened upper blaze. A fragment of a scribed line visible in opened lower blaze. A "W" nail in also in lower blaze.</p> <p>    A rotten Cedar stump which is possibly the orig. 10" Cedar bears S.37°W., 9.7 ft. No scribing or blazes visible.</p> <p>    Also found an unrecorded BT, 40" Cedar stump bears S.38°E., 19.7 ft with a "W" nail visible on a rotted face. Remainder of tree with Weyerhaeuser BT tag is lying nearby.</p> <p>Set - At the location of the 2"x4' post &amp; at record bearing &amp; dist. from orig. 24" Fir stump, I SET a 1"x30" I.P. with brass cap stamped "Douglas County Surveyor ¼ S27 S34 T24S R3W 1981. 20" into the ground and place both wood posts alongside.</p> <p>    8" Fir bears N.67°W., 12.0 ft. scribed ¼ S27 CS BT.</p> <p>    7" AIder bears N.69°E., 21.3 ft. scribed ¼ S27 CS BT</p> <p>    10" Fir bears S.56°E., 8.8 ft. scribed ¼ S34 CS BT.</p> <p>    10" Chinquapin bears S.23°W., 12.4 ft. scribed ¼ S34 CS BTs.</p> <p>    All trees double blazed &amp; have DCS0 BT tags.</p>	
<p>continued next page</p>	

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 11/7/2023 - C.S. File 67/57-14

-----  
Found - DCS0 brass cap on 1" iron pipe, up 10"  
Burned, rotted 28"x2½ ft. stump N.62°E., 11.5 ft.  
(rec. N.64°E., 11.9 ft)  
Mostly burned rotted away 26"x1 ft. Cedar stump  
S.38°E., 19.7 ft.  
Burned, rotted broken off 11"x7 ft. fir snag  
N.67°W., 12.0 ft. fully healed double blaze, add  
3½" mag nail right side center.  
Burned, rotted broken off 18"x6 ft. fir snag  
S.56°E., 8.8 ft. fully healed double blaze, add  
3½" mag nail right side center.  
Burned, away chinquapin now a multi stem shrub  
S.23°W., 12.4 ft. to center of shrub.  
Red & white fence post west 1.5 ft.  
New - 5/8"x30" iron rods with DCS0 plastic caps, proj 3"  
N.32°E., 9.6 ft. N.25°W., 18.0 ft.  
Note - Cor. is 60 ft. north from end of logging spur road.  
Area burnt 9/2020  
Compass decl. 14½°E.  
Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 223221.886 E 241519.994